



<https://www.mygemgroup.com>

PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT

**15209 Lincoln Street
Lake Elsinore, CA 92530**

Report Date: August 1, 2019



Prepared for
Golcheh Group

Prepared by
GEM Group, Inc.
An Environmental Consulting Firm



<https://www.mygemgroup.com>

August 1, 2019

Mr. Ilan Golcheh, President
Golcheh Group
1180 S Beverly Dr.
Los Angeles CA 90035 Suite 300

RE: Phase I Environmental Site Assessment Report
Subject Site Location: 15209 Lincoln Street, Lake Elsinore, CA 92530
Proj. No. 19-9351

Dear Mr. Golcheh,

Attached is an electronic copy of the Phase I Environmental Site Assessment (ESA) report completed by **GEM Group, Inc. (GEM)** for the subject property referenced above. As you will note in the report, our conclusions regarding the environmental condition of the site are summarized both in the ***Executive Summary***, and ***Section 4.0, Findings and Recommendations***.

Please don't hesitate to contact us should you have any questions regarding the results presented in the Phase I ESA report, or if we can be of additional assistance. We look forward to working with you again in the future.

Respectfully yours,

Michael Erving
Junior Geologist

Jen Moser, P.G.
Environmental Professional

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in 40 CFR Part 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property.

Jen Moser, P.G.
Environmental Professional

PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT

**15209 Lincoln Street
Lake Elsinore, CA 92530**

Project No. 19-9351

Prepared by
GEM Group, Inc.
<https://www.mygemgroup.com>

Table of Contents

| | |
|---|------|
| EXECUTIVE SUMMARY | ES-1 |
| 1.0 INTRODUCTION | 1-1 |
| 1.1 SCOPE OF WORK | 1-1 |
| 1.2 EXCEPTIONS AND/OR DELETIONS | 1-2 |
| 1.3 NON-SCOPE ITEMS | 1-2 |
| 1.4 USER RELIANCE | 1-2 |
| 2.0 SITE DESCRIPTION AND RECONNAISSANCE | 2-1 |
| 2.1 SITE FACTS | 2-1 |
| 2.2 SITE PHOTOGRAPHS | 2-1 |
| 2.3 GEOLOGIC AND HYDROGEOLOGIC CONDITIONS | 2-1 |
| 2.4 SITE RECONNAISSANCE | 2-1 |
| 2.4.1 OTHER ENVIRONMENTAL CONDITIONS | 2-3 |
| 2.5 VISUAL OBSERVATIONS, ADJOINING SITES | 2-3 |
| 3.0 REVIEW OF HISTORICAL INFORMATION AND REGULATORY AGENCY RECORDS | 3-1 |
| 3.1 ARCHIVED AGENCY RECORDS SEARCH | 3-1 |
| 3.1.1 STATE WATER QUALITY CONTROL BOARD | 3-1 |
| 3.1.2 DEPARTMENT OF TOXIC SUBSTANCES CONTROL | 3-1 |
| 3.1.3 DEPARTMENT OF CONSERVATION, DIVISION OF OIL, GAS, & GEOTHERMAL RESOURCES | 3-1 |
| 3.1.4 DEPARTMENT OF TRANSPORTATION, NATIONAL PIPELINE MAPPING SYSTEM | 3-1 |
| 3.1.5 SOUTH COAST AIR QUALITY MANAGEMENT DISTRICT | 3-1 |
| 3.1.6 REGIONAL WATER QUALITY CONTROL BOARD, SANTA ANA REGION | 3-1 |
| 3.1.7 ASSESSOR'S OFFICE, RIVERSIDE COUNTY | 3-1 |
| 3.1.8 BUILDING DEPARTMENT, RIVERSIDE COUNTY | 3-2 |
| 3.1.9 FIRE DEPARTMENT, RIVERSIDE COUNTY | 3-2 |
| 3.1.10 ENVIRONMENTAL RESOURCES MANAGEMENT DIVISION, RIVERSIDE COUNTY | 3-2 |
| 3.1.11 DEPARTMENT OF PUBLIC WORKS, RIVERSIDE COUNTY | 3-2 |
| 3.1.12 FIRE DEPARTMENT, CITY OF LAKE ELSINORE | 3-2 |
| 3.1.13 BUILDING DEPARTMENT, CITY OF LAKE ELSINORE | 3-2 |
| 3.2 REVIEW OF REGULATORY AGENCY DATABASES | 3-2 |
| 3.3 REVIEW OF HISTORICAL AERIAL PHOTOGRAPHS | 3-5 |
| 3.4 REVIEW OF HISTORICAL USGS TOPOGRAPHIC MAPS | 3-6 |
| 3.5 REVIEW OF HISTORICAL FIRE INSURANCE MAPS | 3-6 |
| 3.6 REVIEW OF HISTORICAL CITY DIRECTORIES | 3-6 |
| 3.7 PRIOR OR CURRENT AGRICULTURAL LAND USE | 3-7 |
| 3.8 QUESTIONNAIRE AND/OR INTERVIEW | 3-7 |
| 3.9 ADDITIONAL ENVIRONMENTAL DOCUMENTS | 3-7 |
| 3.10 HISTORICAL SITE USE | 3-7 |
| 3.11 TIER 1 VAPOR ENCROACHMENT SCREENING | 3-8 |
| 3.12 REVIEW OF PRELIMINARY TITLE REPORT | 3-9 |

| | | |
|-------|--|-----|
| 3.13 | REVIEW OF APPRAISAL REPORT | 3-9 |
| 3.14 | IDENTIFICATION OF HISTORICAL DATA GAPS | 3-9 |
| 4.0 | FINDINGS AND RECOMMENDATIONS | 4-1 |
| 4.1 | FINDINGS..... | 4-1 |
| 4.1.1 | RECOGNIZED ENVIRONMENTAL CONDITION..... | 4-1 |
| 4.1.2 | HISTORICAL REC | 4-1 |
| 4.1.3 | CONTROLLED REC | 4-1 |
| 4.1.4 | DE MINIMIS CONDITIONS..... | 4-2 |
| 4.1.5 | BUSINESS ENVIRONMENTAL RISK | 4-2 |
| 4.2 | RECOMMENDATIONS | 4-2 |
| 5.0 | REGULATORY AGENCIES..... | 5-1 |
| 6.0 | LIMITATIONS..... | 6-1 |

List of Figures

| | |
|----------|-------------------|
| Figure 1 | Site Location Map |
| Figure 2 | Site Plan |

List of Appendices

| | |
|------------|--|
| Appendix A | Photographs |
| Appendix B | Copies of Records |
| Appendix C | Fire Insurance Maps, City Directories, and Regulatory Agency Databases |
| Appendix D | Resumes |

EXECUTIVE SUMMARY

This report presents results of the Phase I Environmental Site Assessment (ESA) conducted by GEM Group, Inc (GEM) at 15209 Lincoln Street, Lake Elsinore, CA 92530 (see **Figures 1 and 2**). The Phase I ESA, Project No. 19-9351, was conducted in accordance with GEM's Standard Terms and Conditions. The findings and conclusions of this Phase I ESA are based on the information collected and available during the timeframe of this project.

GEM has performed this Phase I ESA of the subject property in conformance with the scope and limitations of the *Environmental Protection Agency, Standards and Practices for All Appropriate Inquiries, 40 CFR Part 312* and the standard practice set forth in the *American Society for Testing and Materials (ASTM) Designation: E1527-13, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process."* Any exceptions to, or deletions from, these practices are described in Section 1.2 of this report.

The subject property is a 6.23-acre vacant dirt lot with weeds and trees.

Historical sources show the subject property developed with multiple structures along the northeast corner from at least 1938 until 1987 when it appears the structures were demolished. The remainder of the subject property was part of an orchard. The onsite orchard appears to have been abandoned and allowed to die prior to the 1980s. The subject property appears to have been undeveloped since at least 1987.

The subject property is not listed in the regulatory databases reviewed. There were no records from various regulatory agencies that identify the potential for adverse environmental impact from the subject and adjoining properties. There are no listed offsite listings with the potential for adverse environmental impact on the subject property.

There are no *recognized environmental conditions (RECs)* identified at the subject property. A *REC* refers to the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment.

Given the findings and conclusions of this Phase I ESA, GEM recommends no further investigation at this time. However, if the subject property is redeveloped for residential use, then soil sampling may be required to determine the presence of pesticides from former orchard use.

1.0 INTRODUCTION

The purpose of this Phase I Environmental Site Assessment (ESA) is to assess (1) the likelihood of contamination at the subject property as a result of either past or present land-use practices; and (2) the potential for future environmental contamination which may occur as a result of current conditions or operations and maintenance activities at either the subject property or properties adjoining the subject property, thereby identifying real or potential environmental or economic impact to the subject property. In this way, the client may satisfy a requirement to qualify for the innocent landowner defense to the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) liability by completing "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial and customary practice."

1.1 SCOPE OF WORK

To meet the objectives stated above, GEM has performed this Phase I ESA of the subject property in conformance with the scope and limitations of the *Environmental Protection Agency, Standards and Practices for All Appropriate Inquiries, 40 CFR Part 312* and the standard practice set forth in the *American Society for Testing and Materials (ASTM) Designation: E1527-13, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process."* Any exceptions to or deletions from these practices are described in Section 1.2.

The scope of work for the Phase I ESA includes the following tasks:

1. Perform a reconnaissance of the subject property for significant surficial signs of chemical release, improper storage of hazardous materials, and surface indications of the presence of underground storage tanks (USTs) or water wells.
2. Provide off site research into the past land use of the subject property.
3. Review locally available aerial photographs for obvious surficial features indicative of past land use. Review available USGS topographic maps, fire insurance maps, and local telephone directories.
4. Review Federal, State and Local Agency files (available during the time frame of this project) for fuel leak and chemical release lists indicating soil and groundwater contamination cases within a ¼ mile radius to the site, as made available through the above-mentioned agency files.

Based on ASTM E1527, Federal, State, and other regulatory agency guidelines, the following presumptions were in force during site reconnaissance and/or evaluation of the subject property for specific hazardous substances:

- Use of asbestos in many products was banned in 1993; however, several categories of building products were not subject to the ban. Thus, existing and even new buildings may lawfully contain asbestos containing building material (ACBM).

- Use of lead-based paint (LBP) for residential use was prohibited in 1978 in concentrations greater than 0.06 percent lead by weight. It should be noted that the use of LBP in commercial and industrial buildings has not been prohibited.
- Fluorescent light ballasts will be considered PCB-free and will not be noted in the report regardless of their date of manufacture, unless GEM is instructed to do otherwise in writing by the client.
- Electrical transformers installed after 1979 must contain less than 50 parts per million of PCB (this is the requirement for the classification, "PCB non-contaminated").

GEM also conducted a "drive-by" survey of the adjoining properties to note the operations which may pose an imminent or potential environmental threat to the subject property.

1.2 EXCEPTIONS AND/OR DELETIONS

There are no known exceptions or deletions.

1.3 NON-SCOPE ITEMS

Evaluation of non-scope items is not required or relevant for compliance with the all appropriate inquiries (AAI) Rule or E1527. Inclusion of any non-scope item in a Phase I report is entirely within the discretion of the user based on its own risk tolerance.

Non-scope items include, but not limited to, ACBM, biological agents, indoor air quality unrelated to releases of hazardous substances or petroleum products into the environment, mold, radon, LBP, and lead in drinking water.

1.4 USER RELIANCE

This report was prepared for the sole use and benefit of **Golcheh Group** (client), and is based, in part, upon documents, writings, and information owned and possessed by our client. Neither this report, nor any of the information contained herein, shall be used or relied upon for any purpose by any person or entity other than our client.

2.0 SITE DESCRIPTION AND RECONNAISSANCE

The subject property is a 6.23-acre vacant dirt lot with weeds and trees.

2.1 SITE FACTS

| | |
|---------------------------------------|---|
| Address Provided by Client: | 15209 Lincoln Street, Lake Elsinore, CA 92530 |
| Assessor's Parcel Number: | 379-111-014 |
| Total Sq. Ft of Parcel (approximate): | 271,379 (6.23-acres) |
| Total Number of Existing Structures: | None |
| Use: | vacant |

2.2 SITE PHOTOGRAPHS

A number of photographs were taken to document the current condition and use of the subject property. The photographs with descriptions can be found in **Appendix A**.

2.3 GEOLOGIC AND HYDROGEOLOGIC CONDITIONS

GEM reviewed pertinent, reasonably ascertainable information on the soil types and groundwater conditions in the vicinity of the subject property. The research does not include the investigation of seismological concerns (i.e., fault lines) that may affect the area of the subject property. Although the existence of faults in an area may be of concern to property owners and residents in that area, it is not considered to be an environmental concern, and so is not usually a component of a Phase I ESA.

The elevation of the subject property is approximately 1,279 feet above mean sea level. The subject property is underlain by Pleistocene to Holocene age sediments of alluviums, gravel, sand, silt, and. The subject property is in the Elsinore Valley Groundwater Basin. Groundwater is primarily used for municipal and irrigational purposes.

Case closure letters for sites in the general vicinity of the subject property indicated that depth to groundwater was encountered at approximately 28 to 63 feet below ground surface (bgs). Groundwater direction in this region is estimated to flow towards Lake Elsinore which is located 0.5 miles southeast of the subject property. These sites are located approximately 0.8 miles from the subject property.

It should be noted that these information is taken from reports for investigations conducted at other properties in the general vicinity and may not be representative of conditions at the subject property. It should be noted that the flow direction and depth of groundwater may be influenced by rainfall, tidal activity (shore properties), and local groundwater pumping operations. It should also be noted that shallower, unreported, perched groundwater zones may occur in the immediate site vicinity.

2.4 SITE RECONNAISSANCE

A visual site reconnaissance of the subject property was conducted on July 21, 2019 to identify observable signs of environmental impairments, including on-site operations and maintenance activities which may

lead to possible environmental impairment.

As a part of the site reconnaissance the subject property was visually inspected for obvious indications of the following:

| DESCRIPTION | COMMENT |
|---|---------|
| Aboveground Storage Tanks (AST) | None |
| Back-up Power Generators (diesel, battery, natural gas) | None |
| Chemical/Hazardous Materials Storage Area | None |
| Creeks/ Canals | None |
| Debris or Debris Stockpile | None |
| Dispenser Islands, Concrete Pads, and/or Cradles (Fuel) | None |
| Dry Cleaner (drop-off, onsite) | None |
| Electrical Transformers (pole or ground) | None |
| Evidence of Soil Borings | None |
| Evidence of Soil Excavation | None |
| Fill Materials | None |
| Drains (trench drains, proximity to HazMat/ waste) | None |
| Floor Staining or Corrosion (inside) | None |
| Forklift (type) | None |
| Grease Drum | None |
| Grease Trap | None |
| Health and Safety Issues (e.g. molds, standing water) | None |
| Heating/Cooling Systems | None |
| Hydraulic Hoists/Elevator (No./Type) | None |
| Industrial Wastewater | None |
| Loading Dock (drain) | None |
| Odors | None |
| Oil Burners/Furnace | None |
| Oil-Water Separator/Clarifier | None |
| Patches (concrete, asphalt) | None |
| Petroleum Containers (No./size/type) | None |
| Pipes of Unknown Uses | None |
| Pits, Ponds, or Lagoons | None |
| Pools of Liquid | None |
| Railroad, spurs | None |
| Septic Systems | None |
| Stained Soil or Pavement | None |
| Stockpiled Soil | None |
| Storm Drains/ Catch Basins | None |
| Stressed Vegetation | None |
| Sump | None |
| Underground Storage Tanks | None |
| Unidentified/Abandoned Containers | None |
| Well, Type? | None |

The compliance review is not intended as a comprehensive compliance audit. Rather, the compliance review is only intended to aid GEM in determining the likelihood that the subject property may have been

impacted by releases of hazardous substances.

2.4.1 OTHER ENVIRONMENTAL CONDITIONS

There are no other environmental conditions other than those previously discussed.

2.5 VISUAL OBSERVATIONS, ADJOINING SITES

During the site reconnaissance, the GEM field assessor performed a "drive-by" survey of the adjoining properties to note operations that may pose an imminent or potential environmental threat to the subject property.

The area is generally occupied by residential and commercial properties.

Adjoining and adjacent properties are:

- **Northwest:** Flannery Street, Lakehouse Apartments (15195 Lincoln Street)
- **Northeast:** Lincoln Street, Brookstone Landing multi-unit commercial building (31733 Riverside Drive)
- **Southeast:** Riverside Drive, Launch Pointe (32040 Riverside Drive)
- **Southwest:** Lakeview Apartments (32209 Riverside Drive)

3.0 REVIEW OF HISTORICAL INFORMATION AND REGULATORY AGENCY RECORDS

3.1 ARCHIVED AGENCY RECORDS SEARCH

GEM submitted requests to review or obtain records from Agencies who have jurisdiction over the subject property. Records, if available, may either provide information about the environmental conditions on the subject property, or establish that no environmentally relevant records are on file for the subject property. A list of regulatory references/sources is provided in **Section 5.0**. Copies of records are included in **Appendix B**.

3.1.1 STATE WATER QUALITY CONTROL BOARD

The State Water Quality Control Board website does not list the subject property with ongoing site assessment or remediation.

3.1.2 DEPARTMENT OF TOXIC SUBSTANCES CONTROL

The Department of Toxic Substances Control website does not list the subject property with ongoing site assessment or remediation.

3.1.3 DEPARTMENT OF CONSERVATION, DIVISION OF OIL, GAS, & GEOTHERMAL RESOURCES

The Department of Conservation, Division of Oil, Gas & Geothermal Resources website does not identify the presence of oil or gas wells on the subject property. The closest listed inactive well is approximately 2 miles northeast of the subject property.

3.1.4 DEPARTMENT OF TRANSPORTATION, NATIONAL PIPELINE MAPPING SYSTEM

The Department of Transportation, National Pipeline Mapping System website does not identify the presence of hazardous materials pipelines on the subject and adjacent properties.

3.1.5 SOUTH COAST AIR QUALITY MANAGEMENT DISTRICT

The South Coast Air Quality Management District does not have permits on file for the subject property.

3.1.6 REGIONAL WATER QUALITY CONTROL BOARD, SANTA ANA REGION

The Santa Ana Regional Water Quality Control Board (SARWQCB) does not have records on file for the subject property.

3.1.7 ASSESSOR'S OFFICE, RIVERSIDE COUNTY

The subject property is an undeveloped 6.23-acre lot. The Assessor's Parcel Number is 379-111-014.

3.1.8 BUILDING DEPARTMENT, RIVERSIDE COUNTY

The Riverside County Building Department does not have records on file for the subject property.

3.1.9 FIRE DEPARTMENT, RIVERSIDE COUNTY

The Riverside County Fire Department does not have the capabilities to provide requested environmental records. Relevant documents are provided by the Riverside County Environmental Resources Management Division.

3.1.10 ENVIRONMENTAL RESOURCES MANAGEMENT DIVISION, RIVERSIDE COUNTY

The Riverside County Environmental Resources Management Division does not have records on file for the subject property.

3.1.11 DEPARTMENT OF PUBLIC WORKS, RIVERSIDE COUNTY

The Riverside County Department of Public Works does not have records on file for the subject property.

3.1.12 FIRE DEPARTMENT, CITY OF LAKE ELSINORE

The City of Lake Elsinore Fire Department was associated with a letter from 1987 to J. Grosvenor referencing standing walls on the subject property after a controlled burn. Debris removal including all foundations was noted to be completed.

3.1.13 BUILDING DEPARTMENT, CITY OF LAKE ELSINORE

Historical building permits on file for the subject property are dated from 1979 through 2016.

A permit from 1979 was associated with public sewer connection to a house. The tenant/owner name was blurred/illegible.

A permit from 1987 was associated with “old house”. The remainder of the permit was blurred and illegible.

A closed complaint from 2016 was associated with junk, trash, and debris on the vacant subject property.

3.2 REVIEW OF REGULATORY AGENCY DATABASES

GEM has also reviewed a vendor-supplied, computer-generated federal, state, and regional one-mile regulatory database search in an effort to determine whether the subject property is listed on an agency environmental database and to identify possible regulatory-listed sites of concern within a one-mile radius of the subject property. In general, these documents list known or suspected hazardous-waste generators, release sites, landfills, unauthorized disposal sites, sites with registered underground storage tanks, and sites currently under investigation for known or suspected environmental violations or releases.

The 2012 Leaking Underground Fuel Tank Guidance Manual published by the California State Water Resource Control Board references numerous plume studies. A 2004 study at 500 UST sites in Los Angeles showed 90 percent of the benzene plumes were less than 350 feet long and 90 percent of the methyl tert-

butyl ether (MTBE) plumes were less than 545 feet long (at 5 micrograms/liter [$\mu\text{g/L}$]). Based on this, GEM assesses the potential environmental impact of petroleum hydrocarbon sites within 0.125 miles (660 feet) of the subject property.

GEM assesses the potential environmental impact of a dry cleaner (PCE sites) with active investigation and remediation on the subject property. Since plumes from dry cleaners are generally longer than petroleum hydrocarbon plumes, GEM assesses the potential environmental impact of PCE sites within 0.25 miles (1,320 feet) of the subject property.

The Federal and State listings are summarized in the table below:

| Government Records | Description | ASTM Search Distance (miles) | Total Listing |
|--|--|------------------------------|---------------|
| Federal | | | |
| National Priority List (NPL) | U.S. Environmental Protection Agency's (EPA) list of national priorities among known or threatened releases of hazardous substances, pollutants, or contaminants throughout the U.S. and its territories. The NPL is intended primarily to guide the EPA in determining which sites warrant further investigation under the Superfund Program. | 1.0 | 0 |
| Delisted NPL | Facilities that have been removed from the NPL. | 0.5 | 0 |
| Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) | EPA's list containing information on the assessment and remediation of current hazardous waste sites pursuant to the CERCLA of 1980. | 0.5 | 0 |
| CERCLIS No Further Action Remedial Action Planned (NFRAP) | Facilities that have been removed and archived from EPA's inventory of CERCLA sites. | 0.5 | 0 |
| Resource Conservation and Recovery Act (RCRA) Corrective Action (CORRACTS) | EPA's database of RCRA facilities associated with treatment, storage, and disposal (TSD) of hazardous waste that are undergoing "corrective action." A "corrective action" order is issued when there has been a release of hazardous waste or constituents into the environment from a RCRA facility. | 1.0 | 0 |
| RCRA non-CORRACTS TSD | EPA's database of facilities which report storage, transportation, treatment, or disposal of hazardous waste. Unlike the RCRA CORRACTS/TSD database, the RCRA Non-CORRACTS/TSD database does not include RCRA facilities where corrective action is required. | 0.5 | 0 |

| Government Records | Description | ASTM Search Distance (miles) | Total Listing |
|---|---|-------------------------------------|----------------------|
| RCRA Generators | EPA's database of facilities that generate hazardous waste as part of their normal business practices. Generators are listed as either large (LQG), small (SQG), or conditionally exempt (CESQG). | property and adjoining properties | 0 |
| Institutional control (IC)/engineering control (EC) | IC includes administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls. EC includes caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health. | property only | 0 |
| Emergency Response Notification System (ERNS) | EPA's database of facilities with reported releases of petroleum and hazardous substances to the air, soil and/or water. | property only | 0 |
| State and Tribal | | | |
| Equivalent NPL | Confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. | 1.0 | 0 |
| Equivalent CERCLIS | Federal Superfund Sites identified by the EPA where the DTSC is actively involved, either in a lead or support capacity, in the investigation and/or remediation currently in progress. | 0.5 | 0 |
| Landfill and/or solid waste disposal sites | Database of solid waste facilities; may include the facility name, class, operation type, area, estimated operational life, and owner. | 0.5 | 0 |
| Leaking underground storage tank (LUST) | List of USTs which have been reported as having had a release. | 0.5 | 0 |
| Registered storage tanks | Database of registered storage tanks | property and adjoining properties | 0 |
| IC/EC | Equivalent to the Federal IC / EC database list | property only | 0 |
| Voluntary cleanup sites | Facilities included as Voluntary Cleanup Program (VCP) | 0.5 | 0 |
| Brownfield sites | Properties addressed by Cooperative Agreement Recipients or Targeted Brownfields Assessments. | 0.5 | 0 |
| Spills, Leaks, Investigation & Cleanup (SLIC) | Sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater. SLIC Program deals with site investigation and corrective action involving sites not overseen by the UST Program and the Well Investigation Program. | 0.5 | 0 |

Supplemental and proprietary historic databases were also reviewed. These databases identified the following listings within 0.25 miles of the subject property:

| Source List | Description | Search Distance (miles) | Total Listing |
|-----------------------------|--|-------------------------|---------------|
| DCF2, DryCleaners, Cleaners | drycleaners reported by the DTSC | 0.25 | 1 |
| Historical listings | listings from historical databases that are no longer updated/used. Listings may have been closed or transferred to active databases | 0.0625-0.25 | 1 |
| Historical Service Station | records dating back to the 1800's that have shown up in historic resources and based on their classification, may have used hazardous materials or petroleum products. | 0.25 | 1 |
| Spill-SSO | database contains private lateral sewage discharges from RWQCB | 0.25 | 1 |

The subject property is not listed in the regulatory databases reviewed.

The following adjoining and immediately adjacent properties are listed in the regulatory databases reviewed:

32040 Riverside Drive is located south across Riverside Drive, (RV Resort Rehabilitation Project, Campground Boat Launch Facility Improvements, & Lake Elsinore Recreation Area):

- Identified stormwater construction site.
- Historical service station in 2002.
- This site is located in between the subject property and Lake Elsinore. This site is located down-gradient from the subject property. Based on the available information, the potential for presence of environmental impact on the subject property appears low at this time.

The Cleaners listing is located 0.15 miles from the subject property. There are no listed violations or investigations at this time.

There are no listings which appear to present potential environmental impact on the subject property at this time.

A copy of the complete database search document and a detailed description of the databases that were searched are included in **Appendix C**.

3.3 REVIEW OF HISTORICAL AERIAL PHOTOGRAPHS

GEM reviewed readily available and reasonably ascertainable aerial photographs of the area of the subject property. Each aerial photograph was reviewed for the subject property and, where applicable, adjacent property use.

Aerial photographs for the years of 1938, 1967, 1978, 1980, 1994, 2005, 2009, 2010, 2012, 2014, 2015, 2016, 2017, and 2018 were reviewed.

The 1938 aerial photograph shows what appears to be multiple structures in the northeastern corner. The remainder of the subject property was vacant land. The immediate vicinity, including the subject property, is agricultural.

The 1967 through 1980 aerial photographs still showed structures along the northeast corner. The remainder of the subject property was part of an orchard. The orchard appears to have been abandoned and allowed to die. The general area was mostly undeveloped with few residential developments.

The 1994 through 2018 aerial photographs showed the subject property as undeveloped vacant land. The general area was developed with mostly residential and commercial structures.

3.4 REVIEW OF HISTORICAL USGS TOPOGRAPHIC MAPS

GEM reviewed readily available and reasonably ascertainable USGS topographic maps of the area of the subject property. USGS topographic maps was reviewed for the subject property and, where applicable, adjacent property use.

USGS topographic maps for the years of 1955, 1957, 1967, 1975, 1985, 1988, 2000, 2001, 2012, and 2015 were reviewed.

The 1955 through 1967 USGS topographic maps showed the general area as orchards with road development.

The 1975 through 2015 USGS topographic maps showed the general area developed with buildings and roads. Orchards were depicted in the vicinity through 2001.

3.5 REVIEW OF HISTORICAL FIRE INSURANCE MAPS

Fire insurance maps are the most detailed historical records of the urban landscape. From 1790 to 1961, nearly every U.S. town and city with populations of 2,000 or more had been surveyed. Shown on these maps, sometimes in great detail, is virtually every building, man-made structure, and business standing at the time the survey was made.

A search of multiple national collections and indexes of historical fire insurance maps was conducted for the above referenced site address. The review of collections and indexes has determined that no historical fire insurance maps are available within these collections and indexes for the referenced site; therefore they are not available and are considered not "reasonably ascertainable" according to ASTM standards.

A copy of the report is included in **Appendix C**.

3.6 REVIEW OF HISTORICAL CITY DIRECTORIES

One of the least known, yet most complete and comprehensive historical sources are historical city or street

directories. GEM reviews historical city or street directories (also known as criss-cross or reverse indexed directories) for information on the past occupants of and activities on the subject property and adjoining properties. If they were reasonably ascertainable, they were reviewed to determine current or past occupants of the subject property.

Historical city or street directories were available for 1985, 1990, 1995, 2000, 2004-2005, and 2007-2008. The listings are provided below:

15209 Lincoln Street (subject property)

- 1985 – 2008 – Address Not Listed

32040 Riverside Avenue (adjacent south property)

- 1985 – California State Park & Recreation Bus Service Campground and Ranger, Lake Elsinore State Park, Watkins Scott
- 1990 – California State Park & Recreation Bus Service Campground and Ranger, Lake Elsinore State Park, Hogue Jas and Linda, Jones Linda K
- 1995 – California State Park & Recreation Campground and Ranger, Lake Elsinore State Park, Dearagon Alejandra
- 2000 – Jones Linda, Lake Elsinore Parks & Recreation Campground
- 2004-2005 – Pyramid Enterprises Inc
- 2007-2008 – Lake Elsinore City Campgrounds, Pyramid Enterprises Inc

A copy of the report is included in **Appendix C**.

3.7 PRIOR OR CURRENT AGRICULTURAL LAND USE

The subject and adjoining properties were used for agriculture from at least 1938.

Agrichemicals are primarily sprayed on the foliage or ground surface. Their potential for subsurface migration to a depth greater than 2 feet below ground surface is not likely as they will have primarily degraded. Also, residual concentrations, if any, would naturally attenuate over time.

If the subject property is redeveloped for residential use, then soil sampling may be required to determine the presence of pesticides.

3.8 QUESTIONNAIRE AND/OR INTERVIEW

An environmental questionnaire was not completed/submitted by the client for the completion of this report.

3.9 ADDITIONAL ENVIRONMENTAL DOCUMENTS

No additional environmental document was provided for review.

3.10 HISTORICAL SITE USE

The chronological historical site use summary below is based on reviewed aerial photographs, maps,

regulatory agency files, interviews, and additional environmental documents:

- 1938 – 1987 – residential/orchards
- 1987 – current – undeveloped vacant lot

3.11 TIER 1 VAPOR ENCROACHMENT SCREENING

Tier 1 vapor encroachment screening (VES) was conducted in general accordance with **ASTM E2600-15, “Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions.”**

The goal of conducting a VES, is to identify a vapor encroachment condition (VEC), which is the presence or likely presence of volatile and toxic vapors in the vadose zone of the subject property caused by the release of vapors from contaminated soil and/or groundwater either on or near the subject property.

The default area of concern is 1/10th mile (0.1 mile = 528 feet) for petroleum hydrocarbon chemicals of concern and 1/3rd mile (0.33 mile = 1,760 feet) for other non-petroleum hydrocarbon chemicals of concern around the subject property. The area of concern may be expanded or reduced based on chemicals of concern, soil characteristics, depth/direction of groundwater, surficial feature and other pertinent information to determine whether a VEC exists or a VEC does not exist.

Vapor intrusion is the general term given to migration of hazardous vapors from any subsurface vapor source, such as contaminated soil or groundwater, through the soil and into an overlying building or structure. These vapors can enter buildings through cracks in basements and foundations, as well as through conduits and other openings in the building envelope. Vapors can also enter structures that are not intended for human occupancy (e.g., sewers, drain lines, access vaults, storage sheds, pump houses) through cracks and other openings.

All types of buildings, regardless of foundation type (e.g., basement, crawl space, slab-on-grade), have openings that render them potentially vulnerable to vapor intrusion. Buildings subject to vapor intrusion include, but are not limited to, residential buildings (e.g., detached single-family homes, trailer or ‘mobile’ homes, multi-unit apartments and condominiums), commercial workplaces (e.g., office buildings, retail establishments), educational and recreational buildings (e.g., schools and gyms), and industrial facilities (e.g., manufacturing plants).

The U.S. Environmental Protection Agency’s *Technical Guide for Assessing and Mitigating the Vapor Intrusion Pathway from Subsurface Vapor Sources to Indoor Air* (OSWER Publication 9200.2-154, June 2015) recommends that 100 feet laterally and vertically is a reasonable initial criterion when considering vapor migration fundamentals. The buffer zone of approximately 100 feet has generally been used in determining which buildings to include in vapor intrusion investigations when significant surface covers are not present, under the assumption that preferential vapor migration routes are absent. Use of the 100-foot buffer zone would be inappropriate for landfills, commercial/industrial releases within an enclosed space, or leaking vapors from natural gas lines.

Based on available information, a VEC does not exist at the subject property.

3.12 REVIEW OF PRELIMINARY TITLE REPORT

A preliminary title report was not available for review.

3.13 REVIEW OF APPRAISAL REPORT

An appraisal report was not available for review.

3.14 IDENTIFICATION OF HISTORICAL DATA GAPS

Data gaps may result from the lack of or inability to obtain information required by ASTM E1527 despite good faith efforts by the environmental professional to gather such information. Data gaps are only significant if “other information and/or professional experience raise reasonable concerns involving the data gap.”

Data gaps may include, but are not limited to, site reconnaissance, interviews, review of standard historical sources, etc. ASTM E1527 requires that all obvious uses of the property shall be identified from the present, back to the property’s first developed use, or back to 1940, whichever is earlier.

During the course of this Phase I ESA, GEM did not identify significant data gaps within the reviewed historic documents for the subject property that could affect the conclusions of this report.

4.0 FINDINGS AND RECOMMENDATIONS

4.1 FINDINGS

The subject property is a 6.23-acre vacant dirt lot with weeds and trees.

Historical sources show the subject property developed with multiple structures along the northeast corner from at least 1938 through 1987 when it appears the structures were demolished. The remainder of the subject property was part of an orchard. The orchard appears to have been abandoned and allowed to die prior to the 1980s. The subject property appears to have been undeveloped since at least 1987.

The subject property is not listed in the regulatory databases reviewed. There were no records from various regulatory agencies that identify the potential for adverse environmental impact from the subject and adjoining properties. There are no listed offsite listings with the potential for adverse environmental impact on the subject property.

4.1.1 RECOGNIZED ENVIRONMENTAL CONDITION

A *REC* refers to the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment.

There are no *RECs* identified at the subject property at this time.

4.1.2 HISTORICAL REC

Historical REC refers to a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

There are no *historical RECs* identified at the subject property at this time.

4.1.3 CONTROLLED REC

Controlled REC is a *REC* resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls).

There are no *controlled RECs* identified at the subject property at this time.

4.1.4 DE MINIMIS CONDITIONS

A *de minimis condition* generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be *de minimis conditions* are not *RECs* nor *controlled RECs*.

There are no *de minimis conditions* at the subject property at this time.

4.1.5 BUSINESS ENVIRONMENTAL RISK

BER is a risk which can have a material environmental or environmentally driven impact on the business associated with the current or planned use of commercial real estate, and is not an issue required to be investigated under this practice. A *BER* may include one or more of the non-scope issues contained in subsection 1.3.

There are no *BERs* associated with the subject property at this time.

4.2 RECOMMENDATIONS

Given the findings and conclusions of this Phase I ESA, GEM recommends no further investigation at this time. However, if the subject property is redeveloped for residential use, then soil sampling may be required to determine the presence of pesticides from former orchard use.

5.0 REGULATORY AGENCIES

| Federal and/or State Agencies | |
|--|---|
| State Water Quality Control Board | http://geotracker.waterboards.ca.gov/ |
| Santa Ana Regional Water Quality Control Board (SARWQCB) | FileReview8@waterboards.ca.gov |
| Department of Toxic Substances Control | http://www.envirostor.dtsc.ca.gov/ |
| Department of Conservation, Division of Oil, Gas, & Geothermal Resources | https://maps.conservation.ca.gov/doggr/wellfinder/#close |
| Department of Transportation, National Pipeline Mapping System | https://pvnpm.phmsa.dot.gov/PublicViewer/ |
| South Coast Air Quality Management District | http://www.aqmd.gov/nav/online-services/public-records |

| County Agencies | |
|----------------------------|---|
| Assessor's Office | http://pic.asrclrec.com/ |
| Environmental Health | http://www.rivcoeh.org |
| Fire Department | RRURecords@fire.ca.gov |
| Building Department | http://rctlma.org/building/Records-Request |
| Department of Public Works | http://rctlma.org/ce/PublicRecordsRequest |

| City Agencies | |
|---------------------|---|
| Fire Department | http://www.lake-elsinore.org/Home/Components/Form |
| Building Department | http://www.lake-elsinore.org/Home/Components/Form |

| Environmental Records Search | |
|------------------------------|---|
| City Directories | https://www.reccheck.com/store/default.asp |
| Fire Insurance Maps | |
| Regulatory Agency Databases | |
| Topographic Maps | https://www.historicaerials.com/ and Google Earth |
| Aerial Photographs | |

6.0 LIMITATIONS

To achieve the study objectives stated in this report, we were required to base GEM conclusions and recommendations on the best information available during the period the Phase I ESA was conducted and within the limits prescribed by GEM client in the contract/authorization agreement and standard terms and conditions.

GEM's professional services were performed using that degree of care and skill ordinarily exercised by environmental consultants practicing in this or similar fields. Resumes are included in **Appendix D**. The findings were mainly based upon examination of historic records, maps, aerial photographs, and governmental agencies lists. The hazardous waste site lists represented in this report represent only a search of the specific government records as listed above. It should be noted that governmental agencies often do not list all sites with environmental contamination; the lists could be inaccurate and/or incomplete. Recommendations are based on the historic land use of the subject property, as well as features noted during the site reconnaissance and examined records. The absence of potential gross contamination sources, historic or present, does not necessarily imply that the subject property is free of any contamination. This report only represents a "due diligence" effort as to the integrity of the subject property. No warranty or guarantee, expressed or implied, is made as to the professional conclusions or recommendations contained in this report. The limitations contained within this report supersede all other contracts or scopes of work, implied or otherwise, except those stated or acknowledged herewith.

This report is not a legal opinion. It does not necessarily comply with requirements defined in any environmental law such as the "innocent landowner defense" or "due diligence inquiry." Only legal counsel retained by the client is competent to determine the legal implications of any information, conclusions, or recommendations in this report. The compliance status is not intended for use as a guide to compliance for the present owner. Its intended use is to identify environmental impairments to the subject property and is not to be used as a guide to the legal compliance to any regulations of any kind.



The findings, conclusions, recommendations, and professional opinions contained in this report have been prepared by the staff of GEM, in accordance with generally accepted professional practices. All cost estimates if provided, are purely estimates, and may not represent the actual costs. The costs provided are for budgetary purposes only.

This report does not address, in any way, septic systems, leach fields, septic tanks, or related health hazards.

Analytical results for samples, if collected, should not be construed as conclusive and binding in any way. All sampling conducted is only for the purposes of general screening and does not imply that all materials, locations, or hazardous materials have been identified nor was the sampling intended to identify every instance of the materials sampled. No interpretation of the sample results is made or implied. GEM relays only the information supplied by the laboratory conducting the analysis.

FIGURES

C:\Users\Bill\Documents\Waser\Phase 1 ESAs\Phase 1 ESAs\15209 Lincoln St Lake Elsinore-SLM.dwg, 7/25/2019 3:01:26 PM




Project Number: 19-9351

Project Address: 15209 Lincoln St.
Lake Elsinore, CA

Figure 1

Site Location Map

C:\Users\Bill\Documents\Moser\Phase I ESAs\Phase I ESAs\15209 Lincoln St Lake Elsinore-SP.dwg, 7/25/2019 2:58:23 PM



Project Number: 19-9351

Project Address: 15209 Lincoln St.
Lake Elsinore, CA

Figure 2

Site Plan

APPENDIX A
PHOTOGRAPHS

Photo-1
Overview of Subject Property (Facing North)



Photo-2
Overview of Subject Property (Facing Northeast)



Photo-3
Overview of Subject Property (Facing Southeast)



Photo-4
Overview of Subject Property (Facing East)



Photo-5
Overview of Subject Property (Facing Northeast)



Photo-6
Overview of Subject Property (Facing South)



Photo-7
Adjoining Southwest Property, Lakeview Apartments
(32209 Riverside Drive, Facing South)



Photo-8
Adjacent Northwest Property, Lakehouse Apartments
(15195 Lincoln Street, Facing Southwest)



Photo-9
Adjacent Southeast Property, Launch Pointe
(32040 Riverside Drive, Facing Southeast)



Photo-10
Adjacent Northeast Property, Brookstone Landing
(31733 Riverside Drive, Facing Northwest)



APPENDIX B
COPIES OF RECORDS



Map Layers

Query Tools

15209 Lincoln St, Lake Elsinore

Help



Print Map

Map Size

ANSI A (8.5 X 11)

OK

Cancel

Map Layers

☒ Accidents (Liquid)

☒ Incidents (Gas)

☒ Gas Transmission Pipelines

☒ Hazardous Liquid Pipelines

☐ LNG Plants

☐ Breakout Tanks

☐ Other Populated Areas (scale dependent)

☐ Highly Populated Areas (scale dependent)


☐ Commercially Navigable Waterways

☐ CNW Inland

☐ CNW Ocean/Great Lakes








☐ State Boundaries


☐ abc Show Labels






Water Flood

-  Plugged Cyclic Steam
-  Plugged Water Source
-  Plugged Observation
-  Plugged well of Unknown type
-  Plugged Multipurpose
-  Plugged Dry Hole
-  Plugged Core Hole
-  Unknown status Gas: Dry Gas; Liquid Gas
-  Unknown status Oil and Gas
-  Unknown status Gas Storage
-  Unknown status Injectors: Air Injector; Gas Disposal; Pressure Maintenance; Steam Flood; Water Disposal; Water Flood
-  Unknown status Cyclic Steam
-  Unknown status Water Source
-  Unknown status Observation
-  Unknown status well of Unknown type
-  Unknown status Multipurpose
-  Unknown status Dry Hole
-  Unknown status Core Hole



POR. RO. LA LAGUNA SEC. 3, T.6S., R.5W.



GEM Group

From: Brittany Palagonia <bpalagonia@aqmd.gov>
Sent: Thursday, July 18, 2019 4:58 PM
To: GEM Group
Cc: OB PR Support NA Docs
Subject: Public Records Request #1397715,
Attachments: - PR - PR Supporting Docs - 7/18/2019 - 1397715 - - - COMPLETION LETTER - BEN KEENEY.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Ben,

Attached is the completion letter regarding your Public Records Request.

Thank you,

Brittany Palagonia

South Coast Air Quality Management District
Public Records | Temporary Senior Office Assistant
Information Management
21865 Copley Drive, Diamond Bar, CA 91765
Direct. 909 396 2362 | Hotline. 909 396 3700
Email. bpalagonia@aqmd.gov | Web. www.aqmd.gov
Please note SCAQMD is closed on Mondays

Information Management
Public Records Unit

Direct Dial (909) 396-3700
Fax: (909) 396-3330

COMPLETION LETTER

July 18, 2019

BEN KEENEY
GEM GROUP
967 KENDALL DR # SUITE A-324
SAN BERNARDINO, CA 92407

Ref: CONTROL NO. 1397715
Received 7/16/2019

Re: P/O'S, EQL'S, NOV'S, I/R'S, & ASBESTOS NOTIFICATIONS FOR 15209 LINCOLN ST, LAKE ELSINORE, CA.

After a thorough search of this agency's records:

NO REQUESTED RECORDS WERE FOUND FOR THE ABOVE-REFERENCED FACILITY OR FACILITY SITE.

If you have any questions, please do not hesitate to contact me. Tuesday through Friday, **8:00 a.m. to 4:30 p.m.**

Sincerely,

BRITTANY PALAGONIA #2362
For COLLEEN PAINE
Public Records Coordinator

bp

lake elsinore gis - Google S

City of Lake Elsinore : GIS M

GIS Home

Map My County v8.1

ArcGIS - My Map

https://gis.countyofriverside.us/Html5Viewer/?viewer=MMC_Public

Apps Bookmarks ERS - Environment... Envirostor GeoTracker NETR Online • Hist... Oil, Gas & Geother... Favorites CalEPA Regulated S... Other bookmarks

RCIT

RIVERSIDE COUNTY

MAP MY COUNTY

Home

Navigation

Drawing/Graphics

Tools

Location Information

Clear Selections

Select Parcel(s)

Search Single APN w/Report

Search by Address

Search By...

Email GIS Staff

Help

Tool Labels

Parcels (1)

Parcels

APN: 379111014

Owner: Not Available Online

Address: 15209 LINCOLN ST
LAKE ELSINORE CA 92530

Assessors Map

Recorded Book/Page: MB 8/377

Summary report for this parcel

Full report for this parcel

Report for all parcels

Show this parcel on Google Maps

Displaying 1 - 1 (Total: 1)

Page 1 of 1

World St...

1:500

0 100 200ft

City of Riverside, County of Riverside, Bureau of Land Management, Esri,

15209

15209 Lake Elsinore

Direction

Photos

9:34 AM
7/15/2019



15209 LINCOLN ST.

CB-022



City of Lake Elsinore

CITY HALL

130 SOUTH MAIN STREET
LAKE ELSINORE, CALIFORNIA 92530

Telephone (714) 674-3125

June 1, 1987

J. Grosvenor
3145 Sports Arena Blvd.
San Diego, Ca 92110

RE: 15209 Lincoln Street

Dear Mr. Grosvenor:

An inspection of the above referenced property shows that some of the walls remain standing after the controlled burn by the Fire Department.

For the abating process to be complete it will be necessary for all debris to be removed, this includes all foundations. If this has not been completed by June 12, 1987 it will be necessary for the City to complete the job through the abating process.

If you have any questions, please contact the Building Division at (714) 674-3124.

Sincerely,

CITY OF LAKE ELSINORE

Robert L. Fink
Senior Building Inspector

RLF/bp

4-002

7-24-87 note from
Assessor's office

West Victoria
Villages

En Co AMIR

Enterprises Inc

15552 McArthur

#345

Travis, CA 92715

Copy May 1987

~~The following information is being furnished to you under the provisions of the Freedom of Information Act, 5 U.S.C. 552, and is not to be distributed outside your agency.~~

Re Inspection

TOTAL FEES DUE \$ 15.00

Receipt # 2

| PLUMBING | FEE'S | ELECTRICAL | FEE'S | MECHANICAL | FEE'S |
|-------------------------|-------|----------------------------|-------|--------------------------|-------|
| Air Repairs | | Generator 0.5 KW - 5-15 KW | | Blower | |
| Auto Wash | | Construction Pole Sub | | Duct Under Ground | |
| Backflow Preventer | | Cooking Unit | | Duct Insulation | |
| Backflow Irrigation | | Pole Lights | | Duct Venting | |
| Caulkers | | Drivers Gas Electric | | Exhaust System Make Up | |
| Dishwasher | | Fan | | Evaporative Cooler | |
| Fixture Transfeal | | F A U | | Heating System & Ducting | |
| Floor Drains | | Fixtures | | 100,000 BTU 100,000 BTU | |
| Floor Sinks | | Outlets | | Hand or Canopy | |
| Gas Service Outlets | | Switches | | Type 1 Type 2 | |
| Interceptors | | Meter Up to 100 amps | | Refrigeration System | |
| P Trap | | Meter Over 100 amps | | 100,000 BTU 100,000 BTU | |
| Rail Drains | | Sub panel | | Range Hood 1200 # | |
| Transfer Sewer | | Transfer meter 15-30 KW | | System Repair Alteration | |
| Sewer Cap | | Transfer meter 50-NA | | Fan Blower | |
| Sewer Cond. Under Bldg. | | Motors 3/4 HP 1/2 | | Booster | |
| Sewer Collectors | | Int. Sump 9-15 HP 18-15- | | Insulator | |
| Sewer Piping | | Sing. Fan, Bl. | | Misc. | |
| Sewer Tank | | Mult. Fan, Res. | | | |
| Swimming Pool Spa | | | | | |
| Water Heater | | Reinspection Fee | | | |
| Water Service | | Issue Fee | | | |
| Septic System | | | | | |
| Misc. | | | | | |

Receipt # 2

ADDITIONAL GRADING FEES
 Plan Check Fee \$
 Permit Fee \$
 Total Fees \$

15.00

15.00

DEVELOPMENT SERVICES REQUIREMENTS
 Zoning Approved By _____ Date 6/11/87
 Building Approved By *Kuss* Date _____
 Application Issued By _____ Date _____

Issue
 Re-inspection

CONSTRUCTION AND PLANNING APPROVALS

Date

Inspector

Temporary Electrical Service or Pole
Soil Pipe Undergrnd.
Property Sewer Line & House Connection
Electrical Conduit Undergrnd.
Steel Reinforcement
Grout
Footings
Slab
Water Pipe Undergrnd.

DO NOT PLACE CONCRETE UNTIL ABOVE IS SIGNED

Floor Joists
Roof Drain
Rough Plumbing
Rough Electrical Conduit
Rough Electric Wiring
Rough Electrical - T Bar Ceiling
Rough Heating & Air Conditioning
Ducts, Ventilating
Gas Pipe - Rough & Test
Floor Sheathing
Roof Framing
Roof Sheathing
T Bar Ceiling
Frame and Flashing
Lathing & Siding
Insulation
Drywall Nailing

DO NOT PLASTER UNTIL THE ABOVE IS SIGNED

Electrical Power Meter Final
Final Electric
Final Heating & Air Conditioning
Final Gas Pipe Test
Hood or Canopy
Final Plumbing
Water Service Final
Gas Service Final
Solar Domestic Final
Backflow Preventer
Backflow Inigation
Landscape Irrigation System

SUB-LIST FINAL

FINAL STRUCTURE & BUILDING

PLANNING FINAL

Electric Release to Edison
Gas Release to Southern California Gas Co

POOL & SPA APPROVALS

Date

Inspector

Pool & Equipment Location
Steel Reinforcement
Forms
Electrical Bonding
Rough Plumbing & Pressure Test
APPROVAL TO COVER GUNITE
Electrical Conduit Undergrnd.
Gas Pipe, (1) Undergrnd., Test
Backwash Lines, P-Trap, (1) Undergrnd.

APPROVAL TO DECK

Backwash & Receptor Final
Heater & Vent Final
Plumbing System Final
Electrical Final
Solar System Final
Fencing & Access Approval

APPROVED FOR PLASTERING

POOL/SPA SYSTEMS FINAL

FIRE DEPT. REQUIREMENT

Underground Hydro
Overhead Hydro
Dry Chemical
Dry Standpipe

FIXED SYSTEM FINAL

OCC. FINAL

HEALTH DEPT. REQUIREMENT

Septic Sys.

FINAL INSPECTION

6/29/77

CITY OF LAKE ELSINORE BUILDING DEPARTMENT

674-3125

SEWER PERMIT - APPLICATION

S 1591

Renewal

| FOR APPLICANT TO FILL IN | | | |
|--|--|-----------------------------|-----------------------|
| LEGAL DESCRIPTION | LOT NUMBER 24 | | |
| BLOCK B | TRACT EL SINORE | | |
| SIZE OF LOT | NUMBER OF BLDGS. NOW ON LOT | | |
| USE OF BUILDINGS | APR 379-110-029-6 | | |
| CONTRACTOR | | | |
| ADDRESS | | | |
| CITY | | TELEPHONE | |
| CONTRACTOR'S STATE LICENSE NUMBER | | CONTRACTOR'S LICENSE NUMBER | |
| NO. | DESCRIPTION OF WORK | FEE | |
| 1 | HOUSE SEWER CONNECTING TO PUBLIC SEWER | \$ 50.00 | |
| | SEPTIC TANK, SEEPAGE PIT OR PITS AND/OR DRAINFIELD | \$ 20.00 | |
| | OVERFLOW SEEPAGE PIT, DRAINFIELD EXTN CESSPOOL, DRYWELL, MANHOLE | \$ 5.00 | |
| | HOUSE SEWER CONNECTING TO PRIVATE DISPOSAL SYSTEM | \$ 5.00 | |
| | CONNECT ADDITIONAL BUILDING OR WORK TO HOUSE SEWER | \$ 5.00 | |
| | ALTER, REPAIR OR ABANDON HOUSE SEWER OR DISPOSAL SYSTEM | \$ 5.00 | |
| | SADDLE MAIN LINE | \$ 50.00 | |
| | EXCAVATION | \$ 2.00 LF | |
| OWNER'S AUTHORIZATION | | PERMIT \$ 2.00 | |
| | | TOTAL FEE 6.00 | |
| I HAVE AT THIS DATE A CONTRACT WITH THE HEREIN NAMED CONTRACTOR TO CONNECT THE ABOVE DESCRIBED EXISTING DWELLING TO THE PUBLIC SEWER. | | | |
| SIGNED THIS _____ DAY OF _____ 19 _____ | | | |
| OWNER OR OWNER'S AGENT _____ | | | |
| ADDRESS _____ | | | |
| I acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and state laws regulating plumbing and sewers. | | | |
| I am properly registered and/or licensed as required by the City of Lake Elsinore and State of California or I am the legal owner of the above described residential property. | | | |
| PERMITTEE'S SIGNATURE _____ | | | |
| BUILDING ADDRESS | | 15249 LINCOLN ST. | |
| NEAREST CROSS STREET | | RIV. DR. | |
| OWNER | | WALNUT GROVE TRUST CO. | |
| MAIL ADDRESS | | 1835 Santa Margarita | |
| CITY | | FALLBROOK | |
| TELEPHONE | | 728-0519 | |
| GROUP | ZONE | PROCESSED BY | |
| | | C-P 26 July 79 | |
| CONNECTION DATA | | | |
| STATION | | DEPTH | |
| MANHOLE REFERENCE | | UPPER LOWER | |
| TYPE OF CONNECTION | | LENGTH FROM M.L. TO P.L. | |
| CURB | | P.L. | |
| STATE ENCROACHMENT PERMIT NUMBER | | | |
| INDUSTRIAL WASTE DISPOSAL CHARGE | | | |
| CONNECTION CHARGE | | | |
| REIMBURSEMENT CHARGE | | | |
| CITY OF LAKE ELSINORE | | DATE | INSPECTOR'S SIGNATURE |
| NEW SEWER | | | |
| CONNECT ADDITIONAL BUILDING OR WORK | | | |
| SEPTIC TANK, SEEP PIT(S) AND/OR DRAINFIELD | | | |
| CESSPOOL <input type="checkbox"/> DRYWELL <input type="checkbox"/> | | | |
| ALTER, REPAIR SEWER OR SEWAGE DISPOSAL SYSTEM | | | |
| BACKFILL SEPTIC TANKS <input type="checkbox"/> SEEP PIT(S) <input type="checkbox"/> CESSPOOLS <input type="checkbox"/> | | | |
| SADDLE MAIN LINE | | | |

This is a Sewer Permit when properly filled out, signed and validated
 Permit void if work is not commenced within 60 days of issuance
 CONTRACTOR'S NOTE: All V.C.P. within street right-of-way to be "Wedgelock" design
 or approved equal. Install 6" Wye cleanout at property line.

Validation

INSPECTOR'S COPY

CITY OF LAKE ELSINORE
BUILDING DEPARTMENT
 674-3125

SOWER
PERMIT - APPLICATION
S 1583

| FOR APPLICANT TO FILL IN | | |
|--|--|------------------------------------|
| LEGAL DESCRIPTION | LOT NUMBER <u>24</u> | |
| BLOCK <u>B</u> | TRACT <u>Elsinore</u> | |
| SIZE OF LOT | NUMBER OF BLDGS. NOW ON LOT | |
| USE OF BUILDINGS | <u>Single House</u> | |
| CONTRACTOR | | |
| ADDRESS | | |
| CITY | TELEPHONE | |
| CONTRACTOR'S STATE LICENSE NUMBER | CONTRACTOR'S LICENSE NUMBER | |
| NO | DESCRIPTION OF WORK | FEE |
| 1 | HOUSE SEWER CONNECTING TO PUBLIC SEWER | \$10.00 |
| | SEPTIC TANK, SEEPAGE PIT OR PITS AND/OR DRAINFIELD | \$10.00 |
| | OVERTFLOW SEEPAGE PIT, DRAINFIELD EXTN | \$5.00 |
| | CESSPOOL DRYWELL, MANHOLE | \$5.00 |
| | HOUSE SEWER CONNECTING TO PRIVATE DISPOSAL SYSTEM | \$5.00 |
| | CONNECT ADDITIONAL BUILDING OR WORK TO HOUSE SEWER | \$5.00 |
| | ALTER REPAIR OR ABANDON HOUSE SEWER OR DISPOSAL SYSTEM | \$5.00 |
| | SADDLE MAIN LINE | \$10.00 |
| | EXCAVATION | \$2.00 LF |
| OWNER'S AUTHORIZATION | | PERMIT <u>S</u> <u>2</u> <u>00</u> |
| | | TOTAL FEE <u>12.00</u> |
| I HAVE AT THIS DATE A CONTRACT WITH THE HEREIN NAMED CONTRACTOR TO CONNECT THE ABOVE DESCRIBED EXISTING DWELLING TO THE PUBLIC SEWER. | | |
| SIGNED THIS _____ DAY OF _____ 19 <u>79</u> | | |
| OWNER OR OWNER'S AGENT | | |
| ADDRESS | | |
| I acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and state laws regulating plumbing and sewers. | | |
| I am properly registered and/or licensed as required by the City of Lake Elsinore and State of California or I am the legal owner of the above described residential property. | | |
| PERMITTEE'S SIGNATURE <u>[Signature]</u> | | |


| | | |
|---|------------------------------|-------------------------------------|
| BUILDING ADDRESS | <u>15309 Lincoln St</u> | |
| NEAREST CROSS STREET | <u>Riverside Drive</u> | |
| OWNER | <u>William J. Jones, Jr.</u> | |
| MAIL ADDRESS | <u>1838 Santa Monica</u> | |
| CITY | <u>Fallbrook</u> | TELEPHONE <u>728-0519</u> |
| GROUP | ZONE | PROCESSED BY <u>C-1 D-1 5-30-79</u> |
| CONNECTION DATA | | |
| STATION | DEPTH | |
| MANHOLE REFERENCE | UPPER LOWER | |
| <div style="text-align: center;"> P A I D MAY 30 1979 CITY OF LAKE ELSINORE </div> | | |
| CONNECTION CHARGE | | |
| REIMBURSEMENT CHARGE | | |
| APPROVALS | | |
| NEW HOUSE SEWER | DATE | INSPECTOR'S SIGNATURE |
| CONNECT ADDITIONAL BUILDING OR WORK | | |
| SEPTIC TANK SEEP. PIT, SI AND/OR DRAINFIELD | | |
| CESSPOOL <input type="checkbox"/> DRYWELL <input type="checkbox"/> | | |
| ALTER REPAIR SEWER OR SEWAGE DISPOSAL SYSTEM | | |
| BACKFILL SEPTIC TANKS <input type="checkbox"/> SEEP PIT(S) <input type="checkbox"/> CESSPOOLS <input type="checkbox"/> | | |
| SADDLE MAIN LINE | | |

This is a Sewer Permit when properly filled out, signed and validated.
 Permit void if work is not commenced within 60 days of issuance.

CONTRACTOR'S NOTE: All V.C.P. within street right-of-way to be "Wedgelock" design or approved equal. Install 6" Wye cleanout at property line.

*Septic System to be Validation
 immediately filled up and
 prior to final inspection.*

INSPECTOR'S COPY



City of Lake Elsinore

CITY HALL

130 SOUTH MAIN STREET
LAKE ELSINORE, CALIFORNIA 92530

Telephone (714) 674-3125

DEPARTMENT OF BUILDING AND SAFETY

STATEMENT OF INTENT

TO: J. Grosvenor
3145 Sports Arena Blvd.
San Diego, CA 92110


DATE: May 20, 1987

Inspection of your property located at: 15209 Lincoln St.
Legal Description: Use CR Base Yr 81 Convey 078979 04180 STT
6.23 acres M/L in Lot 24 Blk B MB 008/377 SD map subs in Els.
Assessor's Parcel Number(s): 379-111-014-3
Lake Elsinore, California reveals the presence of building(s) in
violation of the City of Lake Elsinore Municipal Code, Section
15.08.020 (a), Ordinance No. 587, declared to be a Public
Nuisance. It is the intentions of this Department to condemn and
abate the nuisance as herein described. A preliminary Title/Lot
Book Report has been ordered to determine all parties with an
interest in the property and the cost therefore shall be assessed
against the property owner(s).

If no response is received within fifteen (15) days from receipt
of this statement, a Condemnation and Abatement Notice shall be
issued.

Sincerely,

CITY OF LAKE ELSINORE


Kevin Shear
Chief Building Official

Certified Mail Receipt No. P 479 075 613
Case No. CB-022



HELP

CE Case Details

Print

Close

CE Case 16-3434

CE Case #: 16-3434 Status: Closed: Unfounded
 eFM Case #: N/A Date Opened-Closed: 01/11/2016 - 01/12/2016
 Case assigned to: Castellanos, Edward Follow Up Date: 01/12/2016
 Case initiated by: Complaint Follow Up Action:
 Priority: Medium Open Violations:
 Location: APN: 379111014
 15209 LINCOLN St
 LAKE ELSINORE, CA 92530
 Property Type: Vacant
 Land
 Historic District: None
 Foreclosed : None
 Zone: None
 Neighborhood: None
 Public/Private: None
 Acreage : None

Forms

Location

Validated: Yes

Last Validated on: 2016-01-11 10:01:55

| Address | APN | Additional Information | Census Tract | Block Group | LowModPct | CDBG Eligible | Property Type |
|--|-----------|------------------------|--------------|-------------|-----------|---------------|---------------|
| 15209 LINCOLN St LAKE ELSINORE, CA 92530 | 379111014 | | | | | NO | Vacant Land |

Legal Description

Contacts

| Bill To Contact | Contact Role | Name/Business | Address | Phone | Open Cases |
|-------------------------------------|--------------|---------------|------------|-------|------------|
| <input checked="" type="checkbox"/> | Owner | [REDACTED] | [REDACTED] | | 0 |

Violations

| <i>Date</i> | <i>Violation</i> | <i>Submitted By</i> | <i>Status</i> | <i>Disposition</i> | <i>Notes</i> | <i>CDBG Eligible</i> |
|-------------|--|---------------------|---------------|--------------------|--------------|----------------------|
| 01/11/2016 | 8.18.020(J) Declaration of Nuisance-Junk, Trash and Debris | Teyler, Joyce | Closed | | | Yes |

Status and Follow Up

| <i>Status</i> | <i>Follow Up Date</i> | <i>Follow Up Action</i> |
|-------------------|-----------------------|-------------------------|
| Closed: Unfounded | 01/12/2016 | |

Vehicle 1 Information**Vehicle 2 Information****Vehicle 3 Information****Officer Info**

Officer Badge #: E. Castellanos 1812

Custom Field**Hearing Information****Fee Tracking****AVA Tracking**

Notes

| <u>Entry Date</u> | <u>Entered By</u> | <u>Action Date</u> | <u>Note</u> |
|------------------------------|------------------------|--------------------|---------------------------------|
| 01/12/2016 04:58:49 PM | Castellanos, Edward | 01/12/2016 | No mattresses notice |
| 01/11/2016 10:01:56 AM | Teyler, Joyce | 01/11/2016 | Mattresses dumped on vacant lot |

Attachments

| <u>Upload Date</u> | <u>Title</u> | <u>Description</u> | <u>Uploaded By</u> | <u>Selected for Printing</u> | <u>Attachments</u> |
|--------------------|--------------|--------------------|--------------------|------------------------------|--------------------|
|--------------------|--------------|--------------------|--------------------|------------------------------|--------------------|

No Files Uploaded

**Images marked as Selected are included on View/Print Images page, in the Field Report and in forms. View/Print images button has option to "Include all" if checked.*

Mailings**Time Tracking**

| <u>Employee</u> | <u>Date Worked</u> | <u>Hours</u> | <u>Rate Type</u> | <u>Date Entered</u> | <u>Entered By</u> |
|--------------------|--------------------|--------------|------------------|---------------------|--------------------|
| Edward Castellanos | 01/12/2016 | 0.25 | Regular | 01/12/2016 | Edward Castellanos |
| Total | | 0.25 | | | |

Images

GEM Group

From: Records <records@RIVCO.ORG>
Sent: Monday, July 15, 2019 1:23 PM
To: GEM Group
Subject: 15209 Lincoln

After a thorough search of our records, we are unable to locate any building records for this address or APN.

Our records date back to 1963. All building permit records prior to 1963 have been destroyed.

Also, this address is now located in the City of Lake Elsinore's jurisdiction. You may want to contact their Building Department at (951) 674-3124 to check for any permits they may have issued.

If you have any questions, please contact us @ (951) 955-2017 or with a reply email.

Thank you,

Kim
Records & Information Mgmt.
TLMA, County of Riverside
(951) 955-2017
records@rivco.org



How are we doing? Click the Link and tell us

This email contains information which is confidential and is intended only for use of the recipient(s) named above. If you are not an intended recipient, you are hereby notified that any copying, distribution, disclosure, reliance upon or other use of the contents of this email is strictly prohibited. If you have received this email in error, please notify the sender and destroy your copy of this email. Thank you.

Confidentiality Disclaimer

This email is confidential and intended solely for the use of the individual(s) to whom it is addressed. The information contained in this message may be privileged and confidential and protected from disclosure. If you are not the author's intended recipient, be advised that you have received this email in error and that any use, dissemination, forwarding, printing, or copying of this email is strictly prohibited. If you have received this email in error please delete all copies, both electronic and printed, and contact the author immediately.

GEM Group

From: Records <records@RIVCO.ORG>
Sent: Monday, July 15, 2019 1:23 PM
To: GEM Group
Subject: 15209 Lincoln

Follow Up Flag: Follow up
Flag Status: Flagged

After a thorough search of our records, we are unable to locate any building records for this address or APN.

Our records date back to 1963. All building permit records prior to 1963 have been destroyed.

Also, this address is now located in the City of Lake Elsinore's jurisdiction. You may want to contact their Building Department at (951) 674-3124 to check for any permits they may have issued.

If you have any questions, please contact us @ (951) 955-2017 or with a reply email.

Thank you,

Kim
Records & Information Mgmt.
TLMA, County of Riverside
(951) 955-2017
records@rivco.org



How are we doing? Click the Link and tell us

This email contains information which is confidential and is intended only for use of the recipient(s) named above. If you are not an intended recipient, you are hereby notified that any copying, distribution, disclosure, reliance upon or other use of the contents of this email is strictly prohibited. If you have received this email in error, please notify the sender and destroy your copy of this email. Thank you.

Confidentiality Disclaimer

This email is confidential and intended solely for the use of the individual(s) to whom it is addressed. The information contained in this message may be privileged and confidential and protected from disclosure.

If you are not the author's intended recipient, be advised that you have received this email in error and that any use, dissemination, forwarding, printing, or



County of Riverside
DEPARTMENT OF ENVIRONMENTAL HEALTH

STEVE VAN STOCKUM, DIRECTOR

RELEASE OF RECORDS RESPONSE

July 23, 2019

Service Request No: 45348

GEM
967 Kendall Dr.
San Bernardino, CA 92407
Attn: Ben Keeney

Your request concerning **Hazardous Materials Management Records** has been received and a file search has been conducted. The appropriate action has been taken.

| Site Address | City | Records Found |
|-------------------------------|-----------------------|---|
| 15209 Lincoln St. | Lake Elsinore | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| THIS IS NOT AN INVOICE | Estimated Cost | \$0.00 |

If no records are found, no further action will be taken.

If records are found, please contact our office at (951) 358-5055 to schedule a file review appointment. Records will be available for 30 days from the date of this letter, after which a new Records Request will need to be submitted.

**** There is a clerical records research fee of \$.50 for the first page, plus \$.10 per additional page **Records will not be made available until this fee is paid****

Other fees may apply

Note: Additional time for processing may be required

Appointments are scheduled in one (1) hour increments, not to exceed two (2) hours.

Environmental Protection & Oversight Division
Hazardous Materials Management Branch
Attn: Records Management
P.O. Box 7909
Riverside, CA 92513-7909
Ph: (951) 358-5055
Fax (951) 358-5342

*additional fees may include costs for appt. cancellation/no show, time per service, scan/fax/mail of documents, cd/dvd



County of Riverside Code Enforcement Department

(<http://rctlma.org/ce/>)

Select Language ▼

Search...

Our mission is to enhance public safety and the quality of life in partnership with communities through fair enforcement of the law and codes.

Home (<http://rctlma.org/ce/>)

Regional Offices (<http://rctlma.org/ce/districts>)

Code Forms (<http://rctlma.org/ce/Code-Forms>)

Newsletters (<http://rctlma.org/ce/newsletters>)

Code Brochures (<http://rctlma.org/ce/Code-Brochures>)

Who to Call (<http://rctlma.org/ce/whotocall>)

FAQs (<http://rctlma.org/ce/FAQs>)

PublicRecordsRequest (<http://rctlma.org/ce/PublicRecordsRequest>)

Public Records Request

Instructions:

Please complete the form and submit your request. Upon completion of your request, an invoice will be mailed to you once your records have been produced. Charges on the invoice depend on the size of the request. Payment of direct costs is required prior to receiving the requested records (see below for current rates). Once costs have been paid, copies of the requested records will be available for pick-up. Mail delivery is available for an additional cost.

Direct Costs:

\$0.10 per page copied

\$4.95 mailing cost

Requesting Party Information:

Ben

First

Keeney

Last

967 Kendall Drive, Suite A-324

Return Mailing Address

San Bernardino

City

California

State

92407

Zip Code

GEM@MYGEMGROUP.COM

Email Address

9095270408

Phone Number

Records To Be Requested:

379111014

Assessor's Parcel Number (APN)

15209 Lincoln Street

Subject Property Address

Lake Elsinore

CA

92530

City

State

Zip Code

Please specify records request:

Good morning,

In order to perform an environmental site assessment, we request all available documents such as permits, violations, or inspections (between January 1 1950 and today) for the property at:

15209 Lincoln Street, Lake Elsinore, CA 92530

(ESA 9351 public record request sent 7/15/2019)

Please check all that apply:

☐ Records for inspection

☒ Records to be copied (check one only)

☐ I want to pick up the requested records

☐ I want the requested records mailed to my mailing address listed above

☒ I want the requested records E-mailed to Email address listed above

Submit

Reset

Resources

County of Riverside
(<https://www.countyofriverside.us/>)

TLMA Home Page
(<http://rctlma.org/>)

Building & Safety
(<http://rctlma.org/building>)

Environmental Programs
(<http://rctlma.org/epd>)

Planning
(<http://planning.rctlma.org/>)

Transportation
(<http://rctlma.org/trans>)

General Information

FAQs (</ce/FAQs>)

Newsletters
(</ce/newsletters>)

County Ordinances
(</Departments/Administrative-Services/Useful-Ordinances>)

Graffiti Busters
(<http://www.rcwaste.org/graffiti>)

Code Enforcement

Code Brochures
(</ce/Code-Brochures>)

Most Common Code Violations
(</ce/Most-Common-Code-Violations>)

Survey
(<https://www.surveymonkey.com/r/TLMAFeedBack>)

About Us (</ce/About-Us>)

Employee Recognition
(</ce/EmployeeRecognition>)

Contact Us

Administrative Office
4080 Lemon Street
12th Floor
P.O. Box 1469
Riverside, CA 92501

Phone: (951) 955-2004
(760) 393-3344

Email: Code@rivco.org
(mailto:)



(https://twitter.com/RivCo_Code)



City of Lake Elsinore

CITY HALL

130 SOUTH MAIN STREET
LAKE ELSINORE, CALIFORNIA 92530

Telephone (714) 674-3125

June 1, 1987

J. Grosvenor
3145 Sports Arena Blvd.
San Diego, Ca 92110

RE: 15209 Lincoln Street

Dear Mr. Grosvenor:

An inspection of the above referenced property shows that some of the walls remain standing after the controlled burn by the Fire Department.

For the abating process to be complete it will be necessary for all debris to be removed, this includes all foundations. If this has not been completed by June 12, 1987 it will be necessary for the City to complete the job through the abating process.

If you have any questions, please contact the Building Division at (714) 674-3124.

Sincerely,

CITY OF LAKE ELSINORE

Robert L. Fink
Senior Building Inspector

RLF/bp

4-002

GEM Group

From: WB-RB8-FileReview8 <FileReview8@waterboards.ca.gov>
Sent: Friday, July 19, 2019 4:14 PM
To: GEM Group
Subject: RE: Public records request (GEM group project 9351)

Follow Up Flag: Follow up
Flag Status: Flagged

Good afternoon,

After careful review of our records, we show we have no files for the following site:
15209 Lincoln Street, Lake Elsinore, CA 92530

If we can be of further assistance, please do not hesitate to contact us again.

Thank you,
File Review Desk
3737 Main St. Suite 500
Riverside, CA 92501

From: GEM Group <gem@mygemgroup.com>
Sent: Monday, July 15, 2019 9:27 AM
To: WB-RB8-FileReview8 <FileReview8@waterboards.ca.gov>
Subject: Public records request (GEM group project 9351)

Good morning,

In order to perform an environmental site assessment, we request all available documents such as permits, violations, or inspections (between January 1 1950 and today) for the property at:

15209 Lincoln Street, Lake Elsinore, CA 92530

Regards,

Ben Keeney
Geologist Assistant
GEM Group, Inc.
Mobile (909) 527-0408
Fax (877) 857-2212
<https://www.mygemgroup.com/>

(ESA 9351 public record request sent 7/15/2019)

[Search Again](#)

Property Information Center

Property Information for the 2014-2015 tax year as of January 1, 2014

Property Information

Parcel Number: 379111014-3
Property Address: 15209 LINCOLN ST
 LAKE ELSINORE CA 92530
Legal Description: Lot 24 MB 008/377 MAP SUBS IN
 ELSINORE
Property Type: N/A
Assessment
Description: N/A
Year Built N/A
Square Feet: N/A
Bedroom: N/A
Bath: N/A
Pool: N
Lot Size: 6.23 Acres

Sales Information

Last Recorded 03/2003
Document:
Recording Number: 0218687

Related Property Information

City Sphere: LAKE ELSINORE
Supervisory District: KEVIN JEFFRIES
Landuse Designation: CITY
Agriculture Preserve: NOT IN AN AGRICULTURE
 PRESERVE
School District: LAKE ELSINORE UNIFIED
Water District: WMWD
Fema Flood Plan: FLOOD ZONE 0.2 PCT ANNUAL

Assessed Value Information

Land 758,546
Full Value 758,546
Total Net 758,546

Assessment Information

Assessment Number: 379111014-3
Tax Rate Area: 005-028
Taxability Code: 0-00
Base Year: 2004

Parcel Map

[View Parcel Map](#)

Tax Assessment District CITY OF LAKE ELSINORE ANX
 COUNTY FREE LIBRARY
 COUNTY STRUCTURE FIRE PROTECTION
 CSA 152
 ELS MURRIETA ANZA RESOURCE CONS
 ELSINORE AREA ELEM SCHOOL FUND
 ELSINORE VAL MUN WTR IMP DIST 1
 ELSINORE VALLEY CEMETERY
 ELSINORE VALLEY MUNICIPAL WATER
 FLOOD CONTROL ADMINISTRATION
 FLOOD CONTROL ZONE 3
 GENERAL
 GENERAL PURPOSE
 LAKE ELSINORE UNIF IMP NO 96-1

LAKE ELSINORE UNIFIED
METRO WATER WEST 1302999
MT SAN JACINTO JUNIOR COLLEGE
N.W. MOSQUITO & VECTOR CONT DIST
RANCHO LAGUNA RDV 2
RIV CO REG PARK & OPEN SPACE
RIV. CO. OFFICE OF EDUCATION
WESTERN MUNICIPAL WATER

APPENDIX C
FIRE INSURANCE MAPS
CITY DIRECTORIES
REGULATORY AGENCY DATABASES

Fire Insurance Map Results

REPORT RESULTS



Report Results for:

Jen Moser
GEM Group, Inc. DBA Tom Edwards & Associates
5367 N. Valles Drive
San Bernardino CA 92407

Subject Site:

Client's Project #: undefined
SiteName: undefined
Address: 15209 Lincoln Street
City, State Zip: Lake Elsinore, CA

ERS Order #:
84068

Prepared For:

Name: Jen Moser
Company: GEM Group, Inc. DBA Tom Edwards &
Address: Associates
City, State Zip: 5367 N. Valles Drive
San Bernardino, CA 92407

Date:
July 12, 2019

Historical Fire Insurance Map Search Result:

A search of multiple national collections and indexes of historical fire insurance maps was conducted for the above referenced site address. The review of collections and indexes has determined that no historical fire insurance maps are available within these collections and indexes for the referenced site; therefore they are not available and are considered not "reasonably ascertainable" according to ASTM standards. Environmental Record Search (ERS) certifies that a thorough search of our holdings, various other collections and indexes has been completed.

Thank you for selecting ERS.

Researched by:



Eric Charles Exton

City Directory Research

REPORT RESULTS



Report Results for:

Jen Moser
GEM Group, Inc. DBA Tom Edwards & Associates
5367 N. Valles Drive
San Bernardino, CA 92407
2104709234 CDA
July 18, 2019

Site Information:

15209 Lincoln Street
Lake Elsinore, CA 92530

Subject Site:

Client's Project #: **19-9351**
Address: **15209 Lincoln Street**
City, State Zip: **Lake Elsinore, CA 92530**

ERS Order #:

2104709234 CDAL

Prepared For:

Name: **Jen Moser**
Company: **GEM Group, Inc. DBA Tom Edwards
& Associates**
Address: **5367 N. Valles Drive**
City, State Zip: **San Bernardino, CA 92407**

Date:

July 18, 2019

Prepared By:

Name: **Daniel Johnson**
Phone #: **(714) 669-8096
Ext. 1003**

Enclosed are the results of our:

City Directory Research

Thank you for selecting ***Environmental Record Search!***

Included are the findings of our research of the subject site and immediate adjacent sites.

**Streets Researched: (Subject) 15209 Lincoln Street
(Adjacent) 32000 Block of Riverside Drive**

Years researched which did cover your site or adjacent sites:

| 2007-2008 | 2004-2005 | 2000 | 1995 | 1990 |
|------------------|------------------|-------------|-------------|-------------|
| 1985 | | | | |

Years researched which did NOT cover your site or adjacent sites:

| | | | | |
|--|--|--|--|--|
| | | | | |
|--|--|--|--|--|

ERS's research has been limited to the information presented in the reviewed city directories only. All terms, conditions, and limitations normally associated with work contracted by **ERS** and presented or associated with the city directories are in effect at all times. This letter summary, all its information, and content have been derived from and rely upon the reviewed city directories. **ERS's** research has only been based on these books; **ERS** did not perform any type of independent investigation of any type, including as to the accuracy and/or completeness of the information derived or otherwise obtained from the secondary source or sources.

| Subject Street: | 15209 Lincoln Street |
|-----------------|--|
| Year | Description |
| 2007-2008 | <div> X 15200 GARCIA Sheree 951-245-2860 +7 15212 XXXX 00 15224 B BETTENCOURT Daniel 951-471-1442 0 A EDERLE Hermann 951-609-2806 +7 </div> |
| 2004-2005 | <div> 15197 X ROBIN DR X FLANNRY ST 15200 XXXX 00 15209 XXXX 00 15212 XXXX 00 15224 BETTENCOURT Daniel 951-471-1442 0 15236 XXXX 00 X RIVERSIDE DR ★ 2 BUS 83 RES 41 NEW </div> |
| 2000 | <div> 15197 MIRANDA Daniel 909-245-8473 +0 RIVAS Joe 909-245-3598 +0 ★ STEADFAST Lisa 00 +0 X RIVERSIDE DR 15200 ESQUIVEL Rachel 00 +0 RYLAND Darlene 909-471-1305 9 15209 XXXX 00 15212 AGUILAR Maria 909-245-3965 +0 15224B BETTENCOURT Daniel 909-471-1442 +0 </div> |
| 1995 | <div> 15197 CABELLO Laura 245-3802 3 HERRERA Joseph 674-1828 +5 15209 XXXX 00 15212 TAYLOR Duane 245-4175 +5 TAYLOR Noelle 245-4175 +5 15224 XXXX 00 </div> |
| 1990 | <div> 15197 BENNETT Paul Jr 674-2449 +0 GARNER Dale 674-5301 +0 ★ LAKESIDE APARTMENTS 674-2816 +0 MORROW Sofia C 00 4 PUZACH Pamela G 00 +0 WEBBER Michael F 674-8153 +0 15200 WARNER Donald 674-9638 +0 15209 XXXX 00 15212 HAMIEH Mazen 674-8268 +0 15465 GUMMERT Leo R 00 4 </div> |
| 1985 | <div> 15197 XXXX 00 15209 XXXX 00 15465 XXXX 00 </div> |

| Adjacent Street: | 32000 Block of Riverside Drive |
|------------------|---|
| Year | Description |
| 2007-2008 | <p>31741 ★ ★ BARGAIN CITY 951-471-3718 3 A ★ BIG VALUE MARKET 951-674-7798 3 X JOY ST 32000 LAKE PARK RESORT BARBER Rene 951-245-5951 5 BARBER Terry 951-245-5951 5 BLASKOVICH Fred 951-674-1588 +7 CADMAN Charles 951-245-8794 +7 CROFFORD Roger 951-471-8778 +7 DELEON Celso 951-245-5882 +7 EADY Abbey 951-674-1858 +7 FITZHUGH Hershel 951-471-1514 2 HEIER John 951-471-3828 0 HEIER Lynn 951-471-3828 0 HILL David 951-245-1530 +7 KASOW Irving 951-471-0833 8 ★ LAKE PARK RESORT 951-674-7911 LEAKE D 951-674-2122 1 LINDSEY Veda 951-674-1799 3 MULCAHY M 951-471-2449 +7 PADILLA Oliver 951-674-5983 3 STROOK William 951-678-8514 2 TATE Larry W 951-245-0682 0 THOMPSON Marvin 951-674-7808 +7 32000 32040 ★ LAKE ELSN CITY CAMP GROUNDS 951-471-1212 5 ★ PYRAMID ENTERPRISES INC 951-471-1212 3 X LINCOLN ST 32209 LAKE VIEW APTS ★ AQUARIUS</p> |

| Adjacent Street: | 32000 Block of Riverside Drive |
|------------------|---|
| 2004-2005 | <div> <div>31741 ★ BARGAIN CITY 951-471-3710 +4</div> <div>31741A ★ BIG VALUE MARKET 951-674-7798 7</div> <div>31750 XXXX 00</div> <div>31761 XXXX 00</div> <div>32000 LAKE PARK RESORT</div> <div>BLASKOVICH Fred 951-674-1588 3</div> <div>BOND Bernard L 951-245-9339 9</div> <div>DELATORRE Mario 951-674-2649 2</div> <div>DELEON Celso 951-245-5802 +4</div> <div>10 EADY Abbey 951-674-1558 +4</div> <div>FITZHUGH Marshal 951-471-1514 2</div> <div>HEIER John 951-471-3828 0</div> <div>HEIER Lynn 951-471-3828 0</div> <div>HILL David 951-245-1530 3</div> <div>JOHNS Richard L 951-471-3457 0</div> <div>D8 KASOW Irving 951-471-0833 8</div> <div>★ LAKE PARK RESORT 951-674-7911</div> <div>A18 LAURITSEN Andrew Jr 951-245-2564 2</div> <div>A12 LEAKE D 951-674-2122 1</div> <div>LINDSEY Veda 951-674-1799 +4</div> <div>E11 PADILLA Oliver 951-674-5683 3</div> <div>Y RICHMOND George H 951-678-8582 3</div> <div>ROBERTSON Sherie L 951-674-7379 +4</div> <div>E9 SCOTT Bill 951-674-9263</div> <div>STROOK William 951-678-8514 +4</div> <div>E2 TATE Larry W 951-245-5682 0</div> <div>WILLIAMMEE Lyle 951-471-5471 +4</div> <div>WILLIAMS Doyle 951-245-5489 +4</div> <div>32000</div> <div>32040 ★ PYRAMID 951-471-1212 3</div> <div>ENTERPRISES INC</div> <div>X LINCOLN ST</div> <div>32209 LAKE VIEW APTS</div> </div> |

| Adjacent Street: | 32000 Block of Riverside Drive |
|------------------|--|
| 2000 | <div> <div> 31741 ★ BIG VALUE MARKET 909-674-7798 7 ★ COUCH CLUB VIDEO 909-674-6909 1 ● HAMIDEH Hashem OO +0 31750 ● WESSELINK Richard OO +0 31761 XXXX OO </div> <div> 32000 LAKE PARK RESORT BOND Bernard L 909-245-9339 9 BROOKES Joanne 909-245-0540 +0 HEIER John 909-471-3828 +0 HEIER Lynn 909-471-3828 +0 HIBBARD Chas 909-674-9885 HIBBARD William D 909-245-1384 2 JOHNS Richard L 909-471-3457 +0 JOHNSON Carol 909-674-6666 5 JOHNSON Clarence 909-245-4945 +0 JOHNSON Larry 909-674-6666 5 KASOW Irving 909-471-0833 8 KUPRION N 909-674-3517 ★ LAKE PARK RESORT 909-674-7911 MATTHEWS E Fredk 909-245-2801 3 MESSERALL Thomas 909-674-8165 7 PORTZER J 909-245-4747 2 RESER Phil 909-245-0203 2 RICE Marla 909-245-2843 +0 ROSE Lester M 909-674-1756 5 ROSE Sharon 909-674-1756 5 SCOTT Bill 909-674-9263 SHAFFER Jackie D 909-245-4587 +0 SMITH Keith 909-674-5450 1 TATE Larry W 909-245-5682 +0 32000 32040 ● JONES Linda OO +0 ★ LAKE ELSN CTY 909-471-1212 9 PKS&REC CMP GRND X LINCOLN 32209 LAKE VIEW APTS </div> </div> |

| Adjacent Street: | 32000 Block of Riverside Drive |
|------------------|--|
| 1995 | <div> <div>31741</div> <div>★ COUCH CLUB VIDEO</div> <div>674-6909 1</div> </div> <div> <div>★ CROWN MORTGAGE</div> <div>245-6488 3</div> </div> <div> <div>★ J HABER ATTORNEY SV</div> <div>245-2283 +5</div> </div> <div> <div>★ REALTY WORLD</div> <div>674-6831 1</div> </div> <div> <div>31750</div> <div>XXXX</div> <div>00</div> </div> <div> <div>31761</div> <div>XXXX</div> <div>00</div> </div> <div> <div>32000</div> <div>LAKE PARK RESORT</div> <div></div> </div> <div> <div>ALLEN John W</div> <div>674-6698 2</div> </div> <div> <div>ANTINE Harry J</div> <div>674-2776 +5</div> </div> <div> <div>CROCKETT Linda</div> <div>245-1009 3</div> </div> <div> <div>CURTIS Jackie</div> <div>245-2249</div> </div> <div> <div>CURTIS Ted</div> <div>245-2249</div> </div> <div> <div>DENNING Wm</div> <div>674-8619 +5</div> </div> <div> <div>DUMMERT Eugene</div> <div>245-5842 +5</div> </div> <div> <div>DUNKS Tom</div> <div>674-1909 1</div> </div> <div> <div>HAMILTON Mary</div> <div>245-9645 2</div> </div> <div> <div>HIBBARD Chas</div> <div>674-9885 7</div> </div> <div> <div>HIBBARD Wm D</div> <div>245-1384 2</div> </div> <div> <div>HORGER Jas</div> <div>674-9858 3</div> </div> <div> <div>JASTER Richard A</div> <div>674-9457 7</div> </div> <div> <div>JOHNSON Carol</div> <div>674-6666 +5</div> </div> <div> <div>JOHNSON Larry</div> <div>674-6666 +5</div> </div> <div> <div>KUPRION N</div> <div>674-3517 7</div> </div> <div> <div>★ LAKE PARK RESORT</div> <div>674-7911</div> </div> <div> <div>MATTHEWS E Fredk</div> <div>245-2801 3</div> </div> <div> <div>MILES Freeman Jr</div> <div>245-4812 +5</div> </div> <div> <div>NICOLEN John</div> <div>674-2609</div> </div> <div> <div>NICOLEN Shirley</div> <div>674-2609</div> </div> <div> <div>PORTZER J</div> <div>245-4747 2</div> </div> <div> <div>RESER Phil</div> <div>245-0203 2</div> </div> <div> <div>ROSE Lester M</div> <div>674-1756 +5</div> </div> <div> <div>ROSE Sharon</div> <div>674-1756 +5</div> </div> <div> <div>SCOTT Bill</div> <div>674-9263 9</div> </div> <div> <div>SHIMBOFF Chris R</div> <div>245-0545 +5</div> </div> <div> <div>SMITH Keith</div> <div>674-5450 1</div> </div> <div> <div>TIBBETS John H</div> <div>674-4658 9</div> </div> <div> <div>TUCK Sam</div> <div>674-5140 +5</div> </div> <div> <div>YOUNG Richard</div> <div>245-3936 +5</div> </div> <div> <div>32000</div> <div></div> <div></div> </div> <div> <div>32040</div> <div>★ CA ST PK&REC CMPGRD</div> <div>674-3177 2</div> </div> <div> <div>★ CA ST PK&REC RANGER</div> <div>674-3005</div> </div> <div> <div>DEARAGON Alejandra</div> <div>674-5193 2</div> </div> <div> <div>★ LAKE ELSN CTY PARKS</div> <div>674-3177</div> </div> <div> <div>★ LAKE ELSN STATE PRK</div> <div>674-3177</div> </div> <div> <div>32209</div> <div>LAKE VIEW APTS</div> <div></div> </div> |

| Adjacent Street: | 32000 Block of Riverside Drive |
|------------------|--|
| 1990 | <div> <div>31750 XXXX 00</div> <div>31761 XXXX 00</div> <div>32000 LAKE PARK RESORT</div> <div>ANDERSON Faye 674-4950 9</div> <div>BARNETT Gene 245-1776 +0</div> <div>BASSETT Karen 245-1226 9</div> <div>BEHNEY Ruth 674-5231</div> <div>BELL Paul 674-6041 7</div> <div>BRADLEY Jerry 674-6290 +0</div> <div>BRIDWELL W L 245-1541 +0</div> <div>BROWN Richard L 674-8005 6</div> <div>COLEMAN Danl 245-1711 +0</div> <div>COLWELL Harry 674-5570 7</div> <div>CRENSHAW Joe 00 4</div> <div>DAVIS Harold L 674-3670 +0</div> <div>DUNKS Thos 674-8020</div> <div>DUNKS Vera 674-8020</div> <div>EDGAR Velda 674-4712 +0</div> <div>EMARD Dorothy 245-1802 +0</div> <div>EMARD Ted 245-1802 +0</div> <div>FUTCHER Jas 674-1739 +0</div> <div>GAYLE Starland 674-8449 +0</div> <div>HIBBARD Chas 674-9885 7</div> <div>HUTCHINSON Stuart 00 4</div> <div>JASTER Richard A 674-9457 7</div> <div>JENNINGS Judy 245-1282 +0</div> <div>JOHNS Richard L 674-7100 +0</div> <div>JOHNSON Larry 674-6666 9</div> <div>JOHNSTON J B 245-1786 +0</div> <div>KINDIG James 674-6573 9</div> <div>KIPERS Marlene 674-9665 +0</div> <div>KIPERS Paul 674-9665 +0</div> <div>KUPRION N 674-3517 7</div> <div>★LAKE PARK RESORT 674-7911 5</div> <div>LEONHARDT Cherie 00 +0</div> <div>MCDONAGH Richard B 00 4</div> <div>MOORE Jack E 00 +0</div> <div>MUELLER Ginny 245-1557 +0</div> <div>MURPHY Linda 674-3880 +0</div> <div>MURPHY Robt 674-3880 +0</div> <div>NICHOLS Chas C 245-1035 +0</div> <div>NICOLEN John 674-2609</div> <div>NICOLEN Shirley 674-2609</div> <div>PIERCE Alfred 674-7081 +0</div> <div>PTOLOMEY Alex 674-0031 +0</div> <div>REED Chas 245-1538 +0</div> <div>SCHDELL Lauren 674-5469 +0</div> <div>SCHLICHTING John 674-4815 +0</div> <div>SCHLICHTING John 00 +0</div> <div>SCOTT Bill 674-9263 9</div> <div>SHEPARD Robt 674-9483 +0</div> <div>STUMP Kenneth 674-0390 +0</div> <div>THOMPSON D 245-1717 +0</div> <div>TIBBETS John H 674-4658 9</div> <div>VALERIO Guido 674-9311 7</div> <div>WILSEY F D 674-1984 7</div> <div>32000</div> <div>32040 ★CA ST PK&REC BUS SV 657-0224 4</div> <div>★CA ST PK&REC CMPGRD 674-3177 2</div> <div>★CA ST PK&REC RANGER 674-3005 5</div> <div>HOGUE Jas 674-4100</div> <div>HOGUE Linda 674-4100</div> <div>JONES Linda K 00 4</div> <div>★LAKE ELSN STATE PRK 674-3177</div> <div>32209 LAKE VIEW APTS</div> </div> |

| Adjacent Street: | 32000 Block of Riverside Drive |
|------------------|---|
| 1985 | <div> <div>31750</div> <div>HOGUE JAS</div> <div>674-4100 +5</div> </div> <div> <div>31761</div> <div>XXXX</div> <div>00</div> </div> <div> <div>32000</div> <div>LAKE PARK RESORT</div> <div>674-7911 +5</div> </div> <div> <div>32040</div> <div>CA ST PK&REC BUS SV</div> <div>657-0224 4</div> </div> <div> <div></div> <div>CA ST PK&REC CMPGRD</div> <div>674-3177 2</div> </div> <div> <div></div> <div>CA ST PK&REC RANGER</div> <div>674-3005 +5</div> </div> <div> <div></div> <div>LAKE ELSN STATE PRK</div> <div>674-3177 9</div> </div> <div> <div></div> <div>WATKINS SCOTT</div> <div>674-1364 +5</div> </div> <div> <div>32209</div> <div>APARTMENTS</div> <div></div> </div> |



RecCheck

The Standard for ASTM/AAI Radius Searches

(One Mile Environmental Records Search, Exceeds ASTM 1527/1528 and EPA AII Appropriate Inquiry)

Report Results

REPORT RESULTS



Site Location:

15209 Lincoln Street
Lake Elsinore, CA 92530
(N 33-40-33, W 117-22-31) NAD83

Client:

GEM Group, Inc. DBA Tom Edwards & Associates

TABLE OF CONTENTS

| | |
|---|------------------|
| <u>EXECUTIVE SUMMARY</u> | <u>1</u> |
| <u>SUMMARY OF OCCURRENCES</u> | <u>3</u> |
| <u>POTENTIAL AREAS OF CONCERN/CONTAMINATION SUMMARY</u> | <u>4</u> |
| <u>DATABASE OCCURRENCE SUMMARY</u> | <u>4</u> |
| <u>SITE LOCATION TOPOGRAPHIC MAP</u> | <u>12</u> |
| <u>SITE LOCATION MAP</u> | <u>13</u> |
| <u>1-MILE RADIUS STREET MAP W/OCCURRENCES (MAP1)</u> | <u>14</u> |
| <u>0.25-MILE RADIUS STREET MAP W/OCCURRENCES (MAP2)</u> | <u>15</u> |
| <u>0.0625-MILE RADIUS STREET MAP W/ OCCURRENCES (MAP3)</u> | <u>16</u> |
| <u>1-MILE TOPOGRAPHIC MAP W/OCCURRENCES (MAP4)</u> | <u>17</u> |
| <u>AGENCY DIFFERENCES IN MAPPED LOCATIONS (MAP5)</u> | <u>18</u> |
| <u>SUMMARY OF AGENCY DIFFERENCES</u> | <u>19</u> |
| <u>MAPPED AIR PERMITS WITH POTENTIAL DISPERSION (MAP6)</u> | <u>20</u> |
| <u>LISTED OCCURRENCE DETAILS</u> | <u>21</u> |
| <u>RECORDS SOURCES SEARCHED</u> | <u>30</u> |
| <u>UN-MAPPABLE OCCURRENCES</u> | <u>44</u> |
| <u>DISCLAIMER, LIMITS AND LIABILITIES</u> | <u>45</u> |

EXECUTIVE SUMMARY

INFORMATION ON THE REQUESTED LOCATION

| | |
|---|--|
| Site Address: | 15209 Lincoln Street Lake Elsinore, CA 92530 |
| Client Project Name/Number: | 19-9351 |
| Coordinates: | N 33-40-33, W 117-22-31 (NAD 83) 33.67597, -117.375248 |
| Date of Report | July 12, 2019 |
| ERS Project Number: | 2104709234 |
| Subject Site Listed on the following lists: | Not Listed |
| Subject Site Listed as Map ID#: | N/A |
| USGS 7.5 Minute Quad Map: | Alberhill (2015-03-10) |
| Subject Site Located within a Potential Area of Concern: | No |
| Township, Section and Range: | Township: 06S Range: 05W Section: 02 Baseline: San Bernardino |
| Site Elevation: (feet above or below (-) mean sea level) | 1279 |
| Flood Zone: (FEMA Q3 Digital Data) | Panel: 06059C0375J, Effective Date: 12/3/2009 Zone X - Area of minimal flood hazard, usually depicted on FIRMs as above the 500-year flood level. |
| Fire Insurance Map Coverage: | No |
| Radon Information: | EPA Radon Zone: 2 (Predicted avg for county: 2 to 4 pCi/L) |
| Search Radius Expansion Size: (In Miles) | 0 |
| Soil Type: (USDA Soil Survey Geographic Database) (SSURGO) | Cortina cobbly sandy loam, 2 to 12 percent slopes Map Unit Type: Consociation Hydric: No Drainage Class: Excessively drained General Information: Loamy-skeletal, mixed, nonacid, thermic Typic Xerofluvents |

| | |
|--|----------------|
| Zip Codes Searched for “Un-Mappable” Sites: | Not Researched |
| Occurrence Count: | 11 |

SUMMARY OF OCCURRENCES

| MAP ID | ID/SITE NAME | ADDRESS | DATABASE | STATUS | DISTANCE (MILES) | ELEV DIFF (FEET) |
|---|---|--|-----------------------|--------|------------------|------------------|
| 1 Maps: 1 , 2 , 4 | 491287 RV Resort Rehabilitation Project | 32040 RIVERSIDE DRIVE LAKE ELSINORE | CRSP-CA | Listed | 0.08 E | -2 |
| 1 Maps: 1 , 2 , 4 | 408283 Campground Boat Launch Facility Improvements | 32040 Riverside Drive Lake Elsinore | ENF-SMARTS-CA | Active | 0.08 E | -2 |
| 1 Maps: 1 , 2 , 4 | 212598 LAKE ELSINORE REC. AREA | 32040 RIVERSIDE AVE LAKE ELSINORE | Hist-Service Stations | Listed | 0.08 E | -2 |
| 1 Maps: 1 , 2 , 4 | 4503609 LAKE ELSINORE RECREATIONA AREA | 32040 RIVERSIDE LAKE ELSINORE | Hist-USTReg-CA | Listed | 0.08 E | -2 |
| 2 Maps: 1 , 2 , 4 | 7654 888 Laundromat | 31723 Riverside Dr Lake Elsinore | Cleaners-CA | Listed | 0.15 NE | 0 |
| 3 Maps: 1 , 2 , 4 | CAL000385799 KHALED EISSA DDS INC | 31737 RIVERSIDE DR STE B LAKE ELSINORE | RCRA-NON-US | Listed | 0.15 NE | 2 |
| 4 Maps: 1 , 2 , 4 | 345627 Lake Street Properties LP- Wyroc | 3100 LAKE LAKE ELSINORE | CRSP-CA | Listed | 0.16 S | -10 |
| 5 Maps: 1 , 2 , 4 | CAC002999804 BROOKSTONE LANDING - COMMERCIAL BLDG SUI | 31735 RIVERSIDE DRIVE LAKE ELSINORE | RCRA-NON-US | Listed | 0.19 NE | 6 |
| 6 Maps: 1 , 2 , 4 | 807485 Riverside Dr | Not Reported by Agency | Spills-SSO-CA | Listed | 0.21 SW | -11 |
| 7 Maps: 1 , 2 , 4 | 5650-RSD EVMWD-Lincoln Street Well | 15157 Lincoln St Lake Elsinore | County-Others-CA | Listed | 0.22 NW | 17 |
| 7 Maps: 1 , 2 , 4 | 28969 EVMWD-Lincoln Street Well | 15157 LINCOLN ST LAKE ELSINORE | CRSP-CA | Listed | 0.22 NW | 17 |

POTENTIAL AREAS OF CONCERN/CONTAMINATION SUMMARY

| DATABASE SEARCHED | SUBJECT SITE WITHIN POTENTIAL AREA OF CONCERN | AREAS FOUND WITHIN 1-MILE RADIUS |
|-------------------------------------|---|----------------------------------|
| NPL-R9-US | No | 0 |
| MethaneLF-CA | No | 0 |
| LA-LF-CA | No | 0 |
| Military-Bases-US | No | 0 |
| SGV-Deep-Plumes-CA | No | 0 |
| SGV-Shallow-Plumes-Puente-Valley-CA | No | 0 |
| SGV-Shallow-Plumes-CA | No | 0 |

DATABASE OCCURRENCE SUMMARY

| HIGH RISK* OCCURRENCES IDENTIFIED IN REQUESTED SEARCH RADIUS | | |
|--|---------------------------|-----------------------------|
| DATABASE SEARCHED | DISTANCE SEARCHED (MILES) | HIGH RISK OCCURRENCES FOUND |
| CERCLIS-US | 0.5 | 0 |
| CorAct-Open-CA | 0.5 | 0 |
| County-LUST-Open-CA | 0.5 | 0 |
| County-SLIC-Open-CA | 0.5 | 0 |
| Eval-Hist-Active-CA | 0.5 | 0 |
| Hist-UST-Cleanup-CA | 0.5 | 0 |
| LUST-Open-CA | 0.5 | 0 |
| Military-Active-CA | 1 | 0 |
| NPL-US | 1 | 0 |
| Proposed-NPL-US | 1 | 0 |
| Response-CA | 1 | 0 |
| SAA-Agreements-US | 1 | 0 |
| School-Active-CA | 0.5 | 0 |
| SLIC-Open-CA | 0.5 | 0 |
| State-Response-Active-CA | 1 | 0 |
| Superfund-Active-CA | 1 | 0 |
| Tribal-LUST-Open-Reg9 | 0.5 | 0 |
| VCP-Active-CA | 0.5 | 0 |

* For the purposes of this report, "high risk" occurrences are those that have known contamination and have not received a "case closed" or "no further action" status from the agency that maintains the records.

ASTM/AAI STANDARD RECORD SOURCES SUMMARY

| STANDARD ENVIRONMENTAL RECORD SOURCES | ASTM MIN. SEARCH DIST. / ERS SEARCH DIST. (MILES) | ERS DATABASE NAME | TOTAL LISTINGS | MAP ID #'S |
|---------------------------------------|---|-------------------|----------------|-------------|
| Federal NPL site list | 1.0 / 1.0 | NPL-US | 0 | None Listed |
| | | Proposed-NPL-US | 0 | None Listed |

| | | | | |
|---|--|--------------------------|---|----------------------|
| Federal Delisted NPL site list | 0.5 / 1.0 | Delisted-NPL-US | 0 | None Listed |
| Federal CERCLIS list | 0.5 / 0.5 | CERCLIS-US | 0 | None Listed |
| Federal CERCLIS NFRAP site list | 0.5 / 0.5 | CERCLIS-Archived-US | 0 | None Listed |
| Federal RCRA CORRACTS facilities list | 1.0 / 1.0 | RCRA-COR-US | 0 | None Listed |
| Federal RCRA non-CORRACTS TSD facilities list | 0.5 / 0.5 | RCRA-TSDF-US | 0 | None Listed |
| Federal RCRA generators list | Property and adjoining properties / 0.25 | RCRA-CESQG-US | 0 | None Listed |
| | | RCRA-LQG-US | 0 | None Listed |
| | | RCRA-NON-US | 2 | 3, 5 |
| | | RCRA-SQG-US | 0 | None Listed |
| Federal Inst/Eng control registries | Property Only / 0.25 | Controls-RCRA-US | 0 | None Listed |
| | | Controls-US | 0 | None Listed |
| | | Hist-US-EC | 0 | None Listed |
| | | Hist-US-IC | 0 | None Listed |
| | | LIENS-US | 0 | None Listed |
| Federal ERNS list | Property Only / 0.0625 | ERNS-US | 0 | None Listed |
| State and Tribal-Equivalent NPL | 1.0 / 1.0 | Response-CA | 0 | None Listed |
| | | State-Response-Active-CA | 0 | None Listed |
| | | State-Response-NFA-CA | 0 | None Listed |
| | | State-Response-Other-CA | 0 | None Listed |
| State and Tribal-Equivalent CERCLIS | 0.5 / 0.5 | Superfund-Active-CA | 0 | None Listed |
| | | Superfund-NFA-CA | 0 | None Listed |
| | | Superfund-Other-CA | 0 | None Listed |
| State and Tribal landfill and/or solid waste disposal sites | 0.5 / 0.5 | County-SWF-CA | 0 | None Listed |
| | | Debris-US | 0 | None Listed |
| | | Hist-Dumps-US | 0 | None Listed |
| | | Land-Disposal-CA | 0 | None Listed |
| | | SWIS-CA | 0 | None Listed |
| | | SWLF-US | 0 | None Listed |
| | | Tribal-ODI-US | 0 | None Listed |
| | | County-LUST-CA | 0 | None Listed |
| State and Tribal Leaking Storage Tank Lists | 0.5 / 0.5 | County-LUST-Closed-CA | 0 | None Listed |
| | | County-LUST-Open-CA | 0 | None Listed |
| | | Hist-UST-Cleanup-CA | 0 | None Listed |
| | | LUST-Closed-CA | 0 | None Listed |
| | | LUST-Open-CA | 0 | None Listed |
| | | Tribal-LUST-Closed-Reg9 | 0 | None Listed |
| | | | | |

| | | | | |
|--|--|-----------------------|---|-------------|
| | | Tribal-LUST-Open-Reg9 | 0 | None Listed |
| State and Tribal Registered Storage Tank Lists | Property and adjoining properties / 0.25 | AST-CA | 0 | None Listed |
| | | AST-CRSP-CA | 0 | None Listed |
| | | City-AST-CA | 0 | None Listed |
| | | City-UST-CA | 0 | None Listed |
| | | County-AST-CA | 0 | None Listed |
| | | County-UST-CA | 0 | None Listed |
| | | FEMA-UST-US | 0 | None Listed |
| | | Hist-UST-CA | 0 | None Listed |
| | | Tribal-UST-Reg9 | 0 | None Listed |
| | | UST-Abandoned-CA | 0 | None Listed |
| | | UST-CA | 0 | None Listed |
| | | UST-Closed-CA | 0 | None Listed |
| | | USTComp-CA | 0 | None Listed |
| | | UST-CRSP-CA | 0 | None Listed |
| | | UST-Priority-CA | 0 | None Listed |
| | | UST-Proposed-CA | 0 | None Listed |
| State and Tribal Inst/Eng Control Registries | Property Only / 0.5 | Controls-CA | 0 | None Listed |
| | | Deed-CA | 0 | None Listed |
| | | Hist-Controls-CA | 0 | None Listed |
| | | HWMP-Controls-CA | 0 | None Listed |
| | | Liens-CA | 0 | None Listed |
| State and Tribal Voluntary Cleanup Sites | 0.5 / 0.5 | Military-Active-CA | 0 | None Listed |
| | | Military-NFA-CA | 0 | None Listed |
| | | Military-Other-CA | 0 | None Listed |
| | | School-Active-CA | 0 | None Listed |
| | | School-NFA-CA | 0 | None Listed |
| | | School-Other-CA | 0 | None Listed |
| | | Tribal-VCP-US | 0 | None Listed |
| | | VCP-Active-CA | 0 | None Listed |
| | | VCP-NFA-CA | 0 | None Listed |
| State and Tribal Brownfield Sites | 0.5 / 0.5 | VCP-Other-CA | 0 | None Listed |
| | | BF-MOA-CA | 0 | None Listed |
| | | BF-Tribal-US | 0 | None Listed |

| FEDERAL ASTM/AAI DATABASES | | | | | | | |
|----------------------------|-------------------|--------------|-------------|------------|-----------|-----------|-------|
| DATABASE SEARCHED | DISTANCE SEARCHED | SUBJECT SITE | 0.125 MILES | 0.25 MILES | 0.5 MILES | 1.0 MILES | TOTAL |
| BF-Tribal-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| BF-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| CERCLIS-Archived-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| CERCLIS-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Controls-RCRA-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Controls-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Debris-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |

| FEDERAL ASTM/AAI DATABASES | | | | | | | |
|----------------------------|-------------------|--------------|-------------|------------|-----------|-----------|-------|
| DATABASE SEARCHED | DISTANCE SEARCHED | SUBJECT SITE | 0.125 MILES | 0.25 MILES | 0.5 MILES | 1.0 MILES | TOTAL |
| Delisted-NPL-US | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| ERNS-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| FEMA-UST-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| FTTS-ENF-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Dumps-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Hist-US-EC | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Hist-US-IC | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| HMIS-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| LIENS-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| NPL-US | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| PADS-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| PCB-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Proposed-NPL-US | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| RCRA-CESQG-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| RCRA-COR-US | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| RCRA-LQG-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| RCRA-NON-US | 0.25 | 0 | 0 | 2 | - | - | 2 |
| RCRA-SQG-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| RCRA-TSDF-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| SAA-Agreements-US | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| SWLF-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Tribal-LUST-Closed-Reg9 | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Tribal-LUST-Open-Reg9 | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Tribal-ODI-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Tribal-UST-Reg9 | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Tribal-VCP-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |

| STATE ASTM/AAI DATABASES | | | | | | | |
|--------------------------|-------------------|--------------|-------------|------------|-----------|-----------|-------|
| DATABASE SEARCHED | DISTANCE SEARCHED | SUBJECT SITE | 0.125 MILES | 0.25 MILES | 0.5 MILES | 1.0 MILES | TOTAL |
| AST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| AST-CRSP-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| BF-MOA-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| BZ-HazWaste-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| CERS-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| CHMIRS-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| City-AST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| City-CUPA-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| City-Others-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| City-UST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Controls-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| CorAct-Closed-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| CorAct-Open-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| CorAct-Other-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| CORTESE-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| County-AST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| County-Hist-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| County-LUST-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| County-LUST-Closed-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| County-LUST-Open-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| County-Others-CA | 0.25 | 0 | 0 | 1 | - | - | 1 |
| County-SLIC-Closed-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| County-SLIC-Open-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |

STATE ASTM/AAI DATABASES

| DATABASE SEARCHED | DISTANCE SEARCHED | SUBJECT SITE | 0.125 MILES | 0.25 MILES | 0.5 MILES | 1.0 MILES | TOTAL |
|--------------------------|-------------------|--------------|-------------|------------|-----------|-----------|-------|
| County-SML-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| County-SWF-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| County-UST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| CRSP-CA | 0.25 | 0 | 1 | 2 | - | - | 3 |
| CUPA-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Deed-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| ENF-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| ENF-SMARTS-CA | 0.25 | 0 | 1 | 0 | - | - | 1 |
| ENF-Wastewater-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Eval-Hist-Active-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Eval-Hist-NFA-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Eval-Hist-Other-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| HazWaste-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Controls-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Hist-Cort-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| HIST-R4-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| HIST-SLIC-CV-CLOSED-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| HIST-SLIC-CV-OPEN-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Hist-UST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-UST-Cleanup-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Hist-WIP-Active-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Hist-WIP-Backlog-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Hist-WIP-Historical-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| HWIS-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| HWMP-Controls-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| ICE-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Land-Disposal-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Liens-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| LUST-Closed-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| LUST-Open-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Manifest2-RI | 0.0625 | 0 | 0 | - | - | - | 0 |
| Military-Active-CA | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| Military-NFA-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Military-Other-CA | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| PR-MOA-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Response-CA | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| School-Active-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| School-NFA-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| School-Other-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| SLIC-Closed-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| SLIC-Open-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| SML-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| State-Response-Active-CA | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| State-Response-NFA-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| State-Response-Other-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Superfund-Active-CA | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| Superfund-NFA-CA | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| Superfund-Other-CA | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| SWIS-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| SWRCY-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| UST-Abandoned-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| UST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| UST-Closed-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| USTComp-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| UST-CRSP-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |

STATE ASTM/AAI DATABASES

| DATABASE SEARCHED | DISTANCE SEARCHED | SUBJECT SITE | 0.125 MILES | 0.25 MILES | 0.5 MILES | 1.0 MILES | TOTAL |
|-------------------|-------------------|--------------|-------------|------------|-----------|-----------|-------|
| UST-Priority-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| UST-Proposed-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| VCP-Active-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| VCP-NFA-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| VCP-Other-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |

SUPPLEMENTAL DATABASES

| DATABASE SEARCHED | DISTANCE SEARCHED | SUBJECT SITE | 0.125 MILES | 0.25 MILES | 0.5 MILES | 1.0 MILES | TOTAL |
|--------------------------|-------------------|--------------|-------------|------------|-----------|-----------|-------|
| Air-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| AIR-DIST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| BioFuel-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| CAF-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| CDL-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| CDL-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| CHWF-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Cleaners-CA | 0.25 | 0 | 1 | 0 | - | - | 1 |
| Coal-Ash-Dams-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| County-BI-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Dams-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| DPR-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| DryCleaners-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| EGRID-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| EPA-Watch-List-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| FA-HW-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| FA-HW-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| FA-SWF-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| FRS-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| FTTS-INSP-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| FUDS-US | 1 | 0 | 0 | 0 | 0 | 0 | 0 |
| FUSRAP-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Haulers-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-AFS2-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-AFS-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-AST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-AWS-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-CalFID-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-CALSITES-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-CERCLIS-NFRAP-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-CERCLIS-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-City-UST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Deed-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-DTG-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-ERNS-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-FIFRA-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-FINDS-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-HWS-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-LUSTIS-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| HIST-MLTS-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| HIST-MTBE-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-NPL-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Orange-County-LF-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |


| SUPPLEMENTAL DATABASES | | | | | | | |
|-------------------------|-------------------|--------------|-------------|------------|-----------|-----------|-------|
| DATABASE SEARCHED | DISTANCE SEARCHED | SUBJECT SITE | 0.125 MILES | 0.25 MILES | 0.5 MILES | 1.0 MILES | TOTAL |
| Historical-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Hist-Prop65-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-RCRIS-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Regional-LUST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Regional-Other-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Regional-SLIC-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Regional-Spills-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Regional-SWLF-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Regional-UST-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-SCL-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-SWIS-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-ToxicPits-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-TRIS-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-USGS-WaterWells-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-USTReg-CA | 0.25 | 0 | 1 | 0 | - | - | 1 |
| Hist-WaterWells-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-WMUDS-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| HWT-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| ICIS-Air-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| ICIS-FEC-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| ICIS-NPDES-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| LA-Waste-Haulers-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| Lead-Smelter-2-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Lead-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| LMOP-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| Mines2-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| Mines-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| Mines-CDMG-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| MINES-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| MLTS-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| Mortgage-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| MRDS-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| MWMP-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| NCI-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| NEI-LF-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| NPDES-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| NPDES-SW-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| OGM-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| OGW-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| OSCF-CA | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| PCS-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Perch1-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Perch2-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Project-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| RADINFO-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| RFG-Lab-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| RMP-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| ROD-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| SDWIS-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| SP-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Spills-SSO-CA | 0.25 | 0 | 0 | 1 | - | - | 1 |
| SSTS-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| TierPer-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |
| TOMS-CA | 0.0625 | 0 | 0 | - | - | - | 0 |

SUPPLEMENTAL DATABASES

| DATABASE SEARCHED | DISTANCE SEARCHED | SUBJECT SITE | 0.125 MILES | 0.25 MILES | 0.5 MILES | 1.0 MILES | TOTAL |
|---------------------|-------------------|--------------|-------------|------------|-----------|-----------|-------|
| Tribal-Air-US | 0.25 | 0 | 0 | 0 | - | - | 0 |
| TRIS2000-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| TRIS2010-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| TRIS80-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| TRIS90-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| TSCA-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| UIC2-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| UIC-CA | 0.0625 | 0 | 0 | - | - | - | 0 |
| UMTRA-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| USGS-Waterwells-US | 0.0625 | 0 | 0 | - | - | - | 0 |
| Vapor-Intrusions-US | 0.5 | 0 | 0 | 0 | 0 | - | 0 |
| WDR-CA | 0.25 | 0 | 0 | 0 | - | - | 0 |

PROPRIETARY HISTORIC DATABASES

| DATABASE SEARCHED | DISTANCE SEARCHED | SUBJECT SITE | 0.125 MILES | 0.25 MILES | 0.5 MILES | 1.0 MILES | TOTAL |
|-----------------------------|-------------------|--------------|-------------|------------|-----------|-----------|-------|
| Hist-Agriculture | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Auto Dealers | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Auto Repair | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Chemical Manufacturing | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Chemical-Storage | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Cleaners | 0.25 | 0 | 0 | 0 | - | - | 0 |
| Hist-Convenience | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Disposal-Recycle | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Food-Processors | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Gun-Ranges | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Machine Shop | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Manufacturing | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Metal Plating | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Mining | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Mortuaries | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Oil-Gas | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-OilGas-Refiners | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Other | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Paint-Stores | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Petroleum | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Post-Offices | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Printers | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Rental | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-RV-Dealers | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Salvage | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Service Stations | 0.25 | 0 | 1 | 0 | - | - | 1 |
| Hist-Steel-Metals | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Textile | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Transportation | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Trucking | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Vehicle-Parts | 0.0625 | 0 | 0 | - | - | - | 0 |
| Hist-Vehicle-Washing | 0.0625 | 0 | 0 | - | - | - | 0 |




SITE LOCATION TOPOGRAPHIC MAP

U.S. Geological Survey. Alberhill (2015-03-10) Quadrangle, 7.5 Minute Series

GEM Group, Inc. DBA Tom
Edwards & Associates

15209 Lincoln Street
Lake Elsinore, CA 92530

FIGURE: 1
JOB: 19-9351
DATE: 7/12/2019




SITE LOCATION MAP

GEM Group, Inc. DBA Tom
Edwards & Associates


15209 Lincoln Street
Lake Elsinore, CA 92530

FIGURE: 2
JOB: 19-9351
DATE: 7/12/2019


1-MILE RADIUS STREET MAP W/OCCURRENCES (MAP1)



All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. **Occurrences are shown in three colors** to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.




1-MILE TOPOGRAPHIC MAP W/OCCURRENCES (MAP4)



All plotted occurrences represent approximate locations based on geographic information provided by the respective agency. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. Occurrences are shown in three colors to give a visual indication of the potential risk of the listed occurrence based on the type of list and the current status of the occurrence. Occurrences shown in **RED** are locations with known contamination that have not received a "case closed" or "no further action" status. Occurrences shown in **YELLOW** have been listed by the respective agency, but do not always represent an environmental risk. The detailed status information and description of the listing should be reviewed for further information. Occurrences shown in **GREEN** are occurrences that have active permits or have had contamination in the past but have received a "case closed" or "no further action" status and therefore, do not likely present an environmental risk.

AGENCY DIFFERENCES IN MAPPED LOCATIONS (MAP5)

Note: Occurrences on this map have agency provided coordinates which differ significantly from geocoded locations.




This "AGENCY DIFFERENCES IN MAPPED LOCATIONS (MAP 4)" is fully protected against reproduction in any way, shape or form by ERS Environmental Record Search. ALL applicable laws, copyrights, pending copyrights, trademarks, and any and all applicable Federal and State laws apply at all times. These protections include the concept, procedures, processes, layout, vision, color scheme, mapping layout, legends, data, any and all verbiage, and the entire concept.

SUMMARY OF AGENCY DIFFERENCES

| MAP ID | ID / SITE NAME | ADDRESS / DATABASE | AGENCY COORDINATES | DISTANCE (MILES) | DIRECTION |
|---------------|--|--|---------------------------|-------------------------|------------------|
| 1 | 491287 RV Resort Rehabilitation Project | 32040 RIVERSIDE DRIVE CRSP-CA | -117.37396, 33.67565 | 0.08 | E |
| 1 | 408283 Campground Boat Launch Facility Improvements | 32040 Riverside Drive ENF-SMARTS-CA | -117.3744, 33.6759 | 0.05 | E |

MAPPED AIR PERMITS WITH POTENTIAL DISPERSION (MAP6)

Note: Occurrences on this map are reported in Air Quality databases. Potential air plumes are drawn in the direction of the prevailing wind.
No air quality occurrences were identified in the search radius



All plotted occurrences represent approximate locations based on geographic information provided by the respective agency/source. Actual locations may vary due to numerous reasons such as: the size of the property, accuracy of the provided location, accuracy of the software used to determine the location, etc. Potential air dispersion plumes are depicted to graphically show the direction contaminants may travel based on prevailing wind data and provide a visual screening tool only. Actual direction will vary especially by season. Depending on the actual contaminate, amount released, and other variables, the distance from the source the contaminate may travel can and will vary. Interpretation and review of all the actual relevant data by an environmental professional is recommended before making any decisions, conclusions or otherwise based on the map depictions, air data, and potential air dispersion plumes.

This "MAPPED AIR PERMITS WITH POTENTIAL DISPERSION (MAP 6)" is fully protected against reproduction in any way, shape or form by ERS Environmental Record Search. ALL applicable laws, copyrights, pending copyrights, trademarks, and any and all applicable Federal and State laws apply at all times. These protections include the concept, procedures, processes, layout, vision, color scheme, mapping layout, legends, data, any and all verbiage, and the entire concept.

LISTED OCCURRENCE DETAILS

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|---|--------|--------------|---|----------|
| CRSP-CA | Listed | 0.08 miles E | 1277 ft (2 ft lower than site) | 1 |
| SITE NAME | | | MAPS | ID |
| RV Resort Rehabilitation Project | | | 1 , 2 , 4 | 491287 |
| ADDRESS | | | CITY | ZIP |
| 32040 RIVERSIDE DRIVE | | | LAKE ELSINORE | 92530 |
| DETAILS | | | | |
| <p>Site Regulated Program Information Site ID: 491287 Site EI ID: 857469 Agency Provided Latitude: 33.67565 Agency Provided Longitude: -117.37396</p> <p>Program Description: Construction Storm Water</p> <p>Evaluation Information : Not Reported : Violation Information : Not Reported : Enforcement Information : Not Reported : Chemical Information : Not Reported : Coordinate Information : Not Reported :</p> | | | | |

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|--|--------|--------------|---|----------|
| ENF-SMARTS-CA | Active | 0.08 miles E | 1277 ft (2 ft lower than site) | 1 |
| SITE NAME | | | MAPS | ID |
| Campground Boat Launch Facility Improvements | | | 1 , 2 , 4 | 408283 |
| ADDRESS | | | CITY | ZIP |
| 32040 Riverside Drive | | | Lake Elsinore | 92530 |

DETAILS

Enforcement ID: 408283
 Facility ID: 810493
 Regulatory Measure ID: 416214
 Waste Discharge ID: Not Reported
 Order/Resolution Number: Not Reported
 Regional Water Board number: 8
 Agency: City of Lake Elsinore
 Agency Type: City/Town Agency
 Regulatory Measure Type: Region 8 MS4 CIPs
 Facility/Site County: Riverside
 Coverage Status: Terminated
 Enforcement Status: Active
 Enforcement Type: Verbal Communication
 Effective Date: 7/28/2011
 Termination Date: 3/5/2013
 Enforcement Adoption Date: 2/21/2012
 Enforcement Effective Date: 2/21/2012
 Enforcement Description: Verbal communication - 20120221 - email question - Rita said she was looking forward to inspection report to see what they did wrong.
 Initial Assessed Amount: Not Reported
 Total Assessment Amount: Not Reported
 Liability \$ Amount: Not Reported
 Liability \$ Paid: Not Reported
 Project \$ Amount: Not Reported
 Project \$ Completed: Not Reported
 Total \$ Paid/Completed: Not Reported
 Agency Provided Latitude: 33.675899
 Agency Provided Longitude: -117.374401

[More Details Link](#)

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|-------------------------|--------|--------------|---|----------|
| Hist-Service Stations | Listed | 0.08 miles E | 1277 ft (2 ft lower than site) | 1 |
| SITE NAME | | | MAPS | ID |
| LAKE ELSINORE REC. AREA | | | 1 , 2 , 4 | 212598 |
| ADDRESS | | | CITY | ZIP |
| 32040 RIVERSIDE AVE | | | LAKE ELSINORE | 92530 |

| DETAILS | | | | |
|---|--|--|--|--|
| AS OF DATE: 1/3/2002 SITE TYPE: STATE TANK TYPE: UST COUNTY: RIVERSIDE | | | | |

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|--------------------------------|--------|--------------|---|----------|
| Hist-USTReg-CA | Listed | 0.08 miles E | 1277 ft (2 ft lower than site) | 1 |
| SITE NAME | | | MAPS | ID |
| LAKE ELSINORE RECREATIONA AREA | | | 1 , 2 , 4 | 4503609 |
| ADDRESS | | | CITY | ZIP |
| 32040 RIVERSIDE | | | LAKE ELSINROE | 92530 |
| DETAILS | | | | |
| Reported Date: 1998 | | | | |

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|--------------------|--------|---------------|---|----------|
| Cleaners-CA | Listed | 0.15 miles NE | 1279 ft (0 ft higher than site) | 2 |
| SITE NAME | | | MAPS | ID |
| 888 Laundromat | | | 1 , 2 , 4 | 7654 |
| ADDRESS | | | CITY | ZIP |
| 31723 Riverside Dr | | | Lake Elsinore | 92530 |

DETAILS

Facility and Program Information
 County: Riverside
 Executive First Name: Not Reported
 Executive Last Name: Not Reported
 Professional Title: Not Reported
 Executive Title: Not Reported
 Executive Gender: Not Reported
 ZIP Four: 7813
 Carrier Route: C027
 Delivery Point Barcode: 237
 Metro Area: Riverside, CA
 Neighborhood: Lake Edge District
 Phone Number Combined: (951) 471-8889
 Fax Number Combined: 0
 Toll Free Number Combined: 0
 Website: Not Reported
 Company Description: Not Reported
 Primary SIC Code: 721501
 Primary SIC Description: Laundries-Self Service
 Primary SIC Ad Size: Not Reported
 Primary SIC Year Appeared: 2012
 SIC Code 1: 721101
 SIC Code 1 Description: Laundries
 SIC Code 1 Ad Size: Not Reported
 SIC Code 1 Year Appeared: Not Reported
 SIC Code 2: 721501
 SIC Code 2 Description: Laundries-Self Service

[More Details Link](#)

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|--------------------------|--------|---------------|---|--------------|
| RCRA-NON-US | Listed | 0.15 miles NE | 1281 ft (2 ft higher than site) | 3 |
| SITE NAME | | | MAPS | ID |
| KHALED EISSA DDS INC | | | 1 , 2 , 4 | CAL000385799 |
| ADDRESS | | | CITY | ZIP |
| 31737 RIVERSIDE DR STE B | | | LAKE ELSINORE | 92530 |

DETAILS

Additional details may be found online using the following link:

http://oaspub.epa.gov/enviro/fii_query_dtl_disp_program_facility?pgm_sys_id_in=CAL000385799&pgm_sys_acrnm_in=RCRAINFO

Source Type: Implementer
 Generator Status Universe: N
 Generator Status: Non-Generator
 NAICS1: ALL OTHER WASTE MANAGEMENT SERVICES
 Active Site Indicator: H----
 Owner Name: KHALED EISSA
 Operator Name: ROSA CRUZ
 In Handler Universes: Y
 In a Universe: Y
 Short Term Generator: N
 Importer Activity: N
 Mixed Waste Generator: N
 Transporter Activity: Y
 Transfer Facility: N
 Recycler Activity: N
 Onsite Burner Exemption: N
 Furnace Exemption: N
 Underground Injection Activity: N
 Receives Waste From Off-site: N
 Universal Waste: N
 Universal Waste Destination Facility: Y
 Used Oil Universe: NNNNNNN
 Federal Universal Waste: N
 Active Site Federally Regulated TSDF: -----

[More Details Link](#)

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|---------------------------------|--------|--------------|---|----------|
| CRSP-CA | Listed | 0.16 miles S | 1269 ft (10 ft lower than site) | 4 |
| SITE NAME | | | MAPS | ID |
| Lake Street Properties LP-Wyroc | | | 1 , 2 , 4 | 345627 |
| ADDRESS | | | CITY | ZIP |
| 3100 LAKE | | | LAKE ELSINORE | 92530 |

DETAILS

Site Regulated Program Information

Site ID: 345627

Site EI ID: 206567

Agency Provided Latitude: 33.72923

Agency Provided Longitude: -117.39341

Program Description: Waste Discharge Requirements

Evaluation Information

Evaluation Date: 3/8/2017

Violations Found? (Y/N): No

Evaluation General Type: Compliance Evaluation Inspection

Evaluation Type: RWQCB Type B compliance inspection

Evaluation Note(s): Not Reported

Evaluation Division: Water Boards

Evaluation Program: WDR

Evaluation Source: CIWQS

Violation Information

: Not Reported

:Enforcement Information

: Not Reported

:Chemical Information

: Not Reported

:Coordinate Information

[More Details Link](#)

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|--|--------|---------------|---|--------------|
| RCRA-NON-US | Listed | 0.19 miles NE | 1285 ft (6 ft higher than site) | 5 |
| SITE NAME | | | MAPS | ID |
| BROOKSTONE LANDING - COMMERCIAL BLDG SUI | | | 1 , 2 , 4 | CAC002999804 |
| ADDRESS | | | CITY | ZIP |
| 31735 RIVERSIDE DRIVE | | | LAKE ELSINORE | 92530 |

DETAILS

Additional details may be found online using the following link:

http://oaspub.epa.gov/enviro/fii_query_dtl_disp_program_facility?pgm_sys_id_in=CAC002999804&pgm_sys_acrnm_in=RCRAINFO

Source Type: Implementer
 Generator Status Universe: N
 Generator Status: Non-Generator
 NAICS1: ALL OTHER WASTE MANAGEMENT SERVICES
 Active Site Indicator: -----
 Owner Name: BROOKSTONE LANDING
 Operator Name: CLYDE BRUNNER
 In Handler Universes: N
 In a Universe: N
 Short Term Generator: N
 Importer Activity: N
 Mixed Waste Generator: N
 Transporter Activity: N
 Transfer Facility: N
 Recycler Activity: N
 Onsite Burner Exemption: N
 Furnace Exemption: N
 Underground Injection Activity: N
 Receives Waste From Off-site: N
 Universal Waste: N
 Universal Waste Destination Facility: Y
 Used Oil Universe: NNNNNNN
 Federal Universal Waste: N
 Active Site Federally Regulated TSDF: -----

[More Details Link](#)

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|------------------------|--------|---------------|---|----------|
| Spills-SSO-CA | Listed | 0.21 miles SW | 1268 ft (11 ft lower than site) | 6 |
| SITE NAME | | | MAPS | ID |
| Riverside Dr | | | 1 , 2 , 4 | 807485 |
| ADDRESS | | | CITY | ZIP |
| Not Reported by Agency | | | | |

DETAILS

Facility and Program Information

Event ID: 807485

Certificate ID: 607241

Region: 8

County: Riverside

Agency: Elsinore Valley Municipal Water Dist

Collection SYS: EVMWD Regional Plant CS

WDID: 8SSO10620

Certificate Person Name: Robert O Barnard

Certificate Person Title: Wastewater Collections Superintendent

Certificate Location: 11.03

Certificate Date: 2014.07.03 00.00.00

Spill Location Description: spill came up from a MH housing an air vac for a sewer force main. the sewage ran to the dirt along the edge of the road.

Spill Type: Category 3

Appear PT: Manhole

Appear PT Explanation: Manhole housing an air vac

Reach Surface: No

reach Storm Drainpipe: No

Return To SSS: Not Applicable - Spill did not reach a separate storm drainpipe

Privt Latrl Spill: No

Responsible Party: Not Reported

Final Spill Dest: Unpaved surface

Final Spill Dest Explanation: NA

Spill Volume Reached Land: 15

Spill Volume Discharge A: 0

Spill Volume Discharge B: 0

Spill Volume Discharge C: 0

[More Details Link](#)

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|---|--------|---------------|---|----------|
| County-Others-CA | Listed | 0.22 miles NW | 1296 ft (17 ft higher than site) | 7 |
| SITE NAME | | | MAPS | ID |
| EVMWD-Lincoln Street Well | | | 1 , 2 , 4 | 5650-RSD |
| ADDRESS | | | CITY | ZIP |
| 15157 Lincoln St | | | Lake Elsinore | 92530 |
| DETAILS | | | | |
| Agency: Riverside County Department of Environmental Health, Hazardous Materials Management Branch Note: This is an ERS assigned ID County: Riverside Type: Disclosure Facility List | | | | |

| DATABASE | STATUS | DISTANCE | ELEVATION | MAP ID |
|--|--------|---------------|---|--------|
| CRSP-CA | Listed | 0.22 miles NW | 1296 ft (17 ft higher than site) | 7 |
| SITE NAME | | | MAPS | ID |
| EVMWD-Lincoln Street Well | | | 1 , 2 , 4 | 28969 |
| ADDRESS | | | CITY | ZIP |
| 15157 LINCOLN ST | | | LAKE ELSINORE | 92530 |
| DETAILS | | | | |
| <p>Site Regulated Program Information</p> <p>Site ID: 28969</p> <p>Site EI ID: 10319269</p> <p>Agency Provided Latitude: 33.67823</p> <p>Agency Provided Longitude: -117.377907</p> <p>Program Description: Chemical Storage Facilities</p> <p>Evaluation Information</p> <p>Evaluation Date: 12/6/2017</p> <p>Violations Found? (Y/N): No</p> <p>Evaluation General Type: Compliance Evaluation Inspection</p> <p>Evaluation Type: Routine done by local agency</p> <p>Evaluation Note(s): Not Reported</p> <p>Evaluation Division: Riverside County Department of Env Health</p> <p>Evaluation Program: HMRRP</p> <p>Evaluation Source: CERS</p> <p>Evaluation Date: 4/7/2015</p> <p>Violations Found? (Y/N): No</p> <p>Evaluation General Type: Other/Unknown</p> <p>Evaluation Type: Other, not routine, done by local agency</p> <p>Evaluation Note(s): Not Reported</p> <p>Evaluation Division: Riverside County Department of Env Health</p> <p>Evaluation Program: HMRRP</p> <p>Evaluation Source: CERS</p> <p>More Details Link</p> | | | | |

RECORDS SOURCES SEARCHED

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|---------------------|---|-------------------------------|----------------------------|----------------|
| Air-CA | Air Permits with Emissions | ERS Supplemental Govt Sources | Click Here | None Found |
| AIR-DIST-CA | Air Pollution Control District | ERS Supplemental Govt Sources | Click Here | None Found |
| AST-CA | Historical Aboveground Storage Tanks | State/Tribal UST | Click Here | None Found |
| AST-CRSP-CA | Aboveground Storage Tanks | State/Tribal UST | Click Here | None Found |
| BF-MOA-CA | Brownfield MOA Sites (aka Considered Brownfield Sites, SWRCB MOA, Brownfield Memorandum of Agreement) | State/Tribal Brownfield | Click Here | None Found |
| BF-Tribal-US | Historical Tribal Brownfields | Federal Brownfield | Click Here | None Found |
| BF-US | Brownfields Sites | Federal Brownfields | Click Here | None Found |
| BioFuel-US | Bio Diesel Fuel | ERS Supplemental Govt Sources | Click Here | None Found |
| BZ-HazWaste-CA | Border Zone or Hazardous Waste Property | State/Tribal ASTM Other Med | Click Here | None Found |
| CAF-CA | Confined Animal Facilities | ERS Supplemental Govt Sources | Click Here | None Found |
| CDL-CA | Clandestine Drug Labs | ERS Supplemental Govt Sources | Click Here | None Found |
| CDL-US | National Clandestine Drug Lab Register | ERS Supplemental Govt Sources | Click Here | None Found |
| CERCLIS-Archived-US | CERCLIS sites that have been archived | Federal CERCLIS NFRAP | Click Here | None Found |
| CERCLIS-US | Comprehensive Environmental Response, Compensation, and Liability Information System | Federal CERCLIS | Click Here | None Found |
| CERS-CA | California Environmental Reporting System (CERS) | State/Tribal ASTM Other Med | Click Here | None Found |
| CHMIRS-CA | California Hazardous Material Incident Report System | Emergency Release Reports | Click Here | None Found |
| CHWF-CA | Commercial Offsite Hazardous Waste Facilities | ERS Supplemental Govt Sources | Click Here | None Found |
| City-AST-CA | Underground Storage Tanks | State/Tribal UST | Click Here | None Found |
| City-CUPA-CA | Certified Unified Program Agency | State/Tribal ASTM Other Med | Click Here | None Found |
| City-Others-CA | Hazardous Material Facilities | State/Tribal ASTM Other Med | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|-----------------------|--|--|----------------------------|----------------|
| City-UST-CA | City Agency Underground Storage Tanks | State/Tribal UST | Click Here | None Found |
| Cleaners-CA | Cleaners | ERS Supplemental Govt Sources | Click Here | 1 |
| Coal-Ash-Dams-US | Coal Ash Contaminated Sites and Hazard Dams | ERS Supplemental Govt Sources | Click Here | None Found |
| Controls-CA | California sites with Deed Restrictions or other Controls | State/Tribal Inst/Eng Controls | Click Here | None Found |
| Controls-RCRA-US | RCRA Institutional and Engineering Controls Summary (aka Federal RCRA with Controls) | Federal Institutional/Engineering Controls | Click Here | None Found |
| Controls-US | US CERCLA Sites with Controls (aka US IC/EC, Institutional/Engineering List Controls, Land Use Controls) | Federal Institutional/Engineering Controls | Click Here | None Found |
| CorAct-Closed-CA | Corrective Action Sites | State/Tribal ASTM Other Low | Click Here | None Found |
| CorAct-Open-CA | Corrective Action Sites | State/Tribal ASTM Other High | Click Here | None Found |
| CorAct-Other-CA | Corrective Action Sites | State/Tribal ASTM Other Low | Click Here | None Found |
| CORTESE-CA | Cortese Hazardous Waste & Substances Sites List | State/Tribal ASTM Other Med | Click Here | None Found |
| County-AST-CA | Aboveground Storage Tanks | State/Tribal UST | Click Here | None Found |
| County-BI-CA | Business Inventory | ERS Supplemental Govt Sources | Click Here | None Found |
| County-Hist-CA | Historic Environmental County Listings | State/Tribal ASTM Other Med | Click Here | None Found |
| County-LUST-CA | County Agency Leaking Underground Storage Tanks | State/Tribal LUST | Click Here | None Found |
| County-LUST-Closed-CA | County Agency Leaking Underground Storage Tanks, Closed Cases | State/Tribal LUST | Click Here | None Found |
| County-LUST-Open-CA | County Agency Leaking Underground Storage Tanks, Open Cases | State/Tribal LUST | Click Here | None Found |
| County-Others-CA | Environmental Related Databases | State/Tribal ASTM Other Med | Click Here | 1 |
| County-SLIC-Closed-CA | County SLIC Sites | Emergency Release Reports | Click Here | None Found |
| County-SLIC-Open-CA | County SLIC Sites | Emergency Release Reports | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|---------------------|--|-----------------------------------|----------------------------|----------------|
| County-SML-CA | County Site Mitigation Unit List | State/Tribal ASTM Other Med | Click Here | None Found |
| County-SWF-CA | County Solid Waste Facilities | State/Tribal Landfill/Solid Waste | Click Here | None Found |
| County-UST-CA | County Agency Underground Storage Tanks | State/Tribal UST | Click Here | None Found |
| CRSP-CA | Cal EPA Regulated Site Portal | State/Tribal ASTM Other Med | Click Here | 3 |
| CUPA-CA | Certified Unified Program Agency | State/Tribal ASTM Other Med | Click Here | None Found |
| Dams-CA | California Dams | ERS Supplemental Govt Sources | Click Here | None Found |
| Debris-US | Historical Debris Sites | Federal Solid Waste | Click Here | None Found |
| Deed-CA | Deed Restrictions/Land Use Restrictions | State/Tribal Inst/Eng Controls | Click Here | None Found |
| Delisted-NPL-US | Delisted NPL Sites | Federal Delisted NPL | Click Here | None Found |
| DPR-CA | Pesticide Regulation Licenses | ERS Supplemental Govt Sources | Click Here | None Found |
| DryCleaners-CA | Dry Cleaner Facilities | ERS Supplemental Govt Sources | Click Here | None Found |
| EGRID-US | Emissions & Generation Resource Facilities | ERS Supplemental Govt Sources | Click Here | None Found |
| ENF-CA | Enforcement Actions Data | State/Tribal ASTM Other Med | Click Here | None Found |
| ENF-SMARTS-CA | Storm Water Enforcement Actions | State/Tribal ASTM Other Med | Click Here | 1 |
| ENF-Wastewater-CA | Wastewater Enforcement Actions | State/Tribal ASTM Other Med | Click Here | None Found |
| EPA-Watch-List-US | Historical EPA Watch List | ERS Supplemental Govt Sources | Click Here | None Found |
| ERNS-US | Emergency Response Notification System | Federal ERNS | Click Here | None Found |
| Eval-Hist-Active-CA | EnviroStor Evaluation History Sites | State/Tribal ASTM Other | Click Here | None Found |
| Eval-Hist-NFA-CA | EnviroStor Database Evaluation History NFA Sites | State/Tribal ASTM Other | Click Here | None Found |
| Eval-Hist-Other-CA | EnviroStor Database Evaluation History NFA Sites | State/Tribal ASTM Other | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|-------------------|---|--------------------------------|----------------------------|----------------|
| FA-HW-CA | Financial Assurance, Hazardous Waste | ERS Supplemental Govt Sources | Click Here | None Found |
| FA-HW-US | Financial Assurance, Hazardous Waste | ERS Supplemental Govt Sources | Click Here | None Found |
| FA-SWF-CA | Financial Assurance, Solid Waste Facilities | ERS Supplemental Govt Sources | Click Here | None Found |
| FEMA-UST-US | Historical FEMA Underground Storage Tanks | Federal UST | Click Here | None Found |
| FRS-US | Facility Registry Index (FINDS) | ERS Supplemental Govt Sources | Click Here | None Found |
| FTTS-ENF-US | Historical FIFRA/TSCA Tracking System (FTTS) Enforcement Actions | Federal ASTM Other | Click Here | None Found |
| FTTS-INSP-US | Historical FIFRA/TSCA Tracking System (FTTS) Inspections | ERS Supplemental Govt Sources | Click Here | None Found |
| FUDS-US | Formerly Used Defense Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| FUSRAP-US | Formerly Utilized Sites Remedial Action Program Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Haulers-CA | Registered Waste Tire Haulers Listing | ERS Supplemental Govt Sources | Click Here | None Found |
| HazWaste-CA | Hazardous Waste Facilities | State/Tribal ASTM Other Med | Click Here | None Found |
| Hist-AFS2-US | Historical Air Facility System for Clean Air Act stationary sources | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-AFS-US | Historical Air Facility System for Clean Air Act stationary sources | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Agriculture | Historical Ranches/Farms, Livestock/Agriculture | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-AST-CA | Historical Aboveground Storage Tanks | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Auto Dealers | Historical Auto and Truck Dealers | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Auto Repair | Historical Automotive Repair | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-AWS-CA | Historical Annual Workplan Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-CA | Previously Listed California Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-CalFID-CA | Historical Facility Inventory Database | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-CALSITES-CA | Historical Calsites Database | ERS Supplemental Govt Sources | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|-----------------------------|---|--------------------------------|----------------------------|----------------|
| Hist-CERCLIS-NFRAP-US | Historical CERCLIS-NFRAP | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-CERCLIS-US | Historical CERCLIS Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Chemical Manufacturing | Historical Manufacturing and Distribution of Chemicals, Gases, and/or Solids | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Chemical-Storage | Historical Chemical/Hazardous Use Storage | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-City-UST-CA | Historical Underground Storage Tanks | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Cleaners | Historical Laundry, Cleaners, and Dry Cleaning Services | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Controls-CA | Historical Restricted Use Sites | State/Tribal Inst/Eng Controls | Click Here | None Found |
| Hist-Convenience | Historical Convenience Store with Possible Gas | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Cort-CA | Historical Cortese list | State/Tribal ASTM Other Med | Click Here | None Found |
| Hist-Deed-CA | Historical Deed Restriction Properties | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Disposal-Recycle | Historical Hazardous Disposal/Recycle and Dumps/Waste | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-DTG-CA | Depth to Groundwater | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Dumps-US | Historical Dumps Inventory of 1985 | Federal Solid Waste | Click Here | None Found |
| Hist-ERNS-US | Historical Emergency Response Notification System (ERNS) | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-FIFRA-US | Historical Case Administration Data from National Compliance Database (Federal Insecticide, Fungicide, and Rodenticide Act) | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-FINDS-US | Historical Facility Index System | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Food-Processors | Historical Food Processing Manufacturers | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Gun-Ranges | Historical Gun Ranges/Clubs | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-HWS-CA | Historical Cortese List-Hazardous Waste Substance Site List | ERS Supplemental Govt Sources | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|--------------------------|--|--------------------------------|----------------------------|----------------|
| Hist-LUSTIS-CA | Historical Lust Information System (LUSTIS) | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Machine Shop | Historical Machine Shops, Welding, Machine Repair | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Manufacturing | Historical Sources US: Manufacturing | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Metal Plating | Historical Metal Plating | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Mining | Historical Mining Operations | ERS Exclusive Historic Sources | Click Here | None Found |
| HIST-MLTS-US | Historical Material Licensing Tracking System | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Mortuaries | Historical Crematories/Mortuaries | ERS Exclusive Historic Sources | Click Here | None Found |
| HIST-MTBE-CA | Historical Sites With MTBE (Methyl Tertiary-Butyl Ether) Contamination | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-NPL-US | Historical National Priority List | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Oil-Gas | Historical Oil and Gas Well Related Facilities | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-OilGas-Refiners | Historical Oil/Gas Refiners/Manufacturers/Plants | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Orange-County-LF-CA | Historical Orange County Landfills | ERS Supplemental Govt Sources | Click Here | None Found |
| Historical-CA | Historical Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Other | Historical Environmental Facilities | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Paint-Stores | Historical Paint Stores | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Petroleum | Historical Petroleum Refining/ Manufacturing/ Chemicals | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Post-Offices | Historical Post Offices | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Printers | Historical Printers and Publishers | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Prop65-CA | Historical Prop 65 Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| HIST-R4-CA | Historical sites | State/Tribal ASTM Other Med | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|-------------------------|--|--------------------------------|----------------------------|----------------|
| Hist-RCRIS-US | Historical EPA's Resource Conservation and Recovery Act | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Regional-LUST-CA | Historical Leaking Underground Storage Tanks | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Regional-Other-CA | Historical Toxic Lists, Site Mitigation, and Groundwater Cleanup Program | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Regional-SLIC-CA | Historical Spills and Leak Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Regional-Spills-CA | Historical Industrial Cleanup Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Regional-SWLF-CA | Historical County Landfills and Transfer Stations | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Regional-UST-CA | Historical Underground Storage Tanks | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Rental | Historical Rental Equipment & Yards | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-RV-Dealers | Historical Trailer and Recreational Vehicle Dealers | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Salvage | Historical Vehicle Salvage Yards or Wreckers | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-SCL-CA | Historical California Cerclis Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Service Stations | Historical Service Stations/Vehicle Fueling | ERS Exclusive Historic Sources | Click Here | 1 |
| HIST-SLIC-CV-CLOSED-CA | Historical Central Valley Spills and Leak Sites | Emergency Release Reports | Click Here | None Found |
| HIST-SLIC-CV-OPEN-CA | Historical Central Valley Spills and Leak Sites | Emergency Release Reports | Click Here | None Found |
| Hist-Steel-Metals | Historical Steel Mills/Manufacturers/Foundries/Smelters | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-SWIS-CA | Historical Solid Waste Information System (SWIS) | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Textile | Historical Textile Mills/Manufacturers | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-ToxicPits-CA | Historical Toxic Pits Cleanup Facilities | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Transportation | Historical Transportation Facilities | ERS Exclusive Historic Sources | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|-------------------------|--|--|----------------------------|----------------|
| Hist-TRIS-US | Historical Toxic Release Inventory System | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-Trucking | Historical Trucking, Shipping, Delivery, and/or Storage | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-US | Historical Previously Listed Federal Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-US-EC | Historical Engineering Controls Sites (aka US EC, Engineering Controls, Land Use Controls) | Federal Institutional/Engineering Controls | Click Here | None Found |
| Hist-USGS-WaterWells-CA | Historical Ground Water Site Inventory for California | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-US-IC | Historical Sites with Institutional Controls (aka US IC, Institutional Controls, Land Use Controls) | Federal Institutional/Engineering Controls | Click Here | None Found |
| Hist-UST-CA | Historical Hazardous Substance Storage Information (aka Historical Underground Storage Tanks) | State/Tribal UST | Click Here | None Found |
| Hist-UST-Cleanup-CA | Historic UST Cases Recommended for Closure under UST Cleanup Fund 5 Year Review (aka UST Cleanup Fund Cases) | State/Tribal LUST | Click Here | None Found |
| Hist-USTReg-CA | Historical Underground Storage Tank Registrations Database | ERS Supplemental Govt Sources | Click Here | 1 |
| Hist-Vehicle-Parts | Historical Vehicle Parts | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-Vehicle-Washing | Historical Vehicle/Truck Washing Facilities | ERS Exclusive Historic Sources | Click Here | None Found |
| Hist-WaterWells-US | Historical Public Community Water Supply/Well Head Protection Database | ERS Supplemental Govt Sources | Click Here | None Found |
| Hist-WIP-Active-CA | Historical Well Investigation Program Case List, Active Sites (aka WIP) | State/Tribal ASTM Other Med | Click Here | None Found |
| Hist-WIP-Backlog-CA | Historical Well Investigation Program Case List, Backlog Sites (aka WIP) | State/Tribal ASTM Other Med | Click Here | None Found |
| Hist-WIP-Historical-CA | Historical Well Investigation Program Case List, Historical Sites (aka WIP) | State/Tribal ASTM Other Low | Click Here | None Found |
| Hist-WMUDS-CA | Historical Waste Management Unit Database System | ERS Supplemental Govt Sources | Click Here | None Found |
| HMIS-US | Hazardous Materials Information System | Federal Emergency Release Reports | Click Here | None Found |
| HWIS-CA | Hazardous Waste Information Summary | State/Tribal RCRA Equivalent | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|---------------------|--|--|----------------------------|----------------|
| HWMP-Controls-CA | Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction | State/Tribal Inst/Eng Controls | Click Here | None Found |
| HWT-CA | Hazardous Waste Transporters | ERS Supplemental Govt Sources | Click Here | None Found |
| ICE-CA | Inspection, Compliance, and Enforcement | State/Tribal ASTM Other Med | Click Here | None Found |
| ICIS-Air-US | Integrated Compliance Information System for Air | ERS Supplemental Govt Sources | Click Here | None Found |
| ICIS-FEC-US | Integrated Compliance Information System for Federal Enforcement Data | ERS Supplemental Govt Sources | Click Here | None Found |
| ICIS-NPDES-US | National Pollutant Discharge Elimination System (NPDES) | ERS Supplemental Govt Sources | Click Here | None Found |
| LA-LF-CA | Los Angeles County Landfills | State/Tribal Solid Waste | Click Here | None Found |
| Land-Disposal-CA | Geotracker - Land Disposal Sites (aka Landfills, LDS) | State/Tribal Landfill/Solid Waste | Click Here | None Found |
| LA-Waste-Haulers-CA | Waste Haulers | ERS Supplemental Govt Sources | Click Here | None Found |
| Lead-Smelter-2-US | Historical Lead Smelter Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Lead-US | Lead Smelter Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| Liens-CA | Environmental Liens | State/Tribal Inst/Eng Controls | Click Here | None Found |
| LIENS-US | Superfund Liens | Federal Institutional/Engineering Controls | Click Here | None Found |
| LMOP-US | Landfill Methane Outreach Program | ERS Supplemental Govt Sources | Click Here | None Found |
| LUST-Closed-CA | Geotracker - Leaking Underground Storage Tanks, Closed Cases | State/Tribal LUST | Click Here | None Found |
| LUST-Open-CA | Geotracker - Leaking Underground Storage Tanks, Open Cases | State/Tribal LUST | Click Here | None Found |
| Manifest2-RI | Hazardous Waste Manifest | State/Tribal RCRA Equivalent | Click Here | None Found |
| MethaneLF-CA | Methane Producing Landfills | State/Tribal Other | Click Here | None Found |
| Military-Active-CA | EnviroStor Database Military Active Sites (aka MCS) | State/Tribal Voluntary Cleanup Sites | Click Here | None Found |
| Military-Bases-US | Military Base Boundaries | ERS Supplemental Govt Sources | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|-------------------|---|--------------------------------------|----------------------------|----------------|
| Military-NFA-CA | EnviroStor Database Military Active Sites (aka MCS) | State/Tribal Voluntary Cleanup Sites | Click Here | None Found |
| Military-Other-CA | EnviroStor Database Military Active Sites (aka MCS) | State/Tribal Voluntary Cleanup Sites | Click Here | None Found |
| Mines2-CA | California Mines | ERS Supplemental Govt Sources | Click Here | None Found |
| Mines-CA | Historical Death Valley Mines | ERS Supplemental Govt Sources | Click Here | None Found |
| Mines-CDMG-CA | California Division of Mines and Geology | ERS Supplemental Govt Sources | Click Here | None Found |
| MINES-US | Mines Master Index File | ERS Supplemental Govt Sources | Click Here | None Found |
| MLTS-US | Material Licensing Tracking System | ERS Supplemental Govt Sources | Click Here | None Found |
| Mortgage-CA | Cal Mortgage Facilities | ERS Supplemental Govt Sources | Click Here | None Found |
| MRDS-US | Mineral Resources Data System (MRDS) | ERS Supplemental Govt Sources | Click Here | None Found |
| MWMP-CA | Medical Waste Management Program | ERS Supplemental Govt Sources | Click Here | None Found |
| NCI-CA | Non-Case Information | ERS Supplemental Govt Sources | Click Here | None Found |
| NEI-LF-CA | Historical NEI (National Emission Inventory) Landfill Point Sources | ERS Supplemental Govt Sources | Click Here | None Found |
| NPDES-CA | National Pollutant Discharge Elimination System | ERS Supplemental Govt Sources | Click Here | None Found |
| NPDES-SW-CA | Notice of Intent Data | ERS Supplemental Govt Sources | Click Here | None Found |
| NPL-R9-US | NPL Region 9 Site Boundaries | Federal NPL | Click Here | None Found |
| NPL-US | National Priorities List | Federal NPL | Click Here | None Found |
| OGM-CA | Oil and Gas Monitoring | ERS Supplemental Govt Sources | Click Here | None Found |
| OGW-CA | California Oil and Gas Wells | ERS Supplemental Govt Sources | Click Here | None Found |
| OSCF-CA | Orphan Site Cleanup Fund | ERS Supplemental Govt Sources | Click Here | None Found |
| PADS-US | PCB Registration Database System | Federal ASTM Other | Click Here | None Found |
| PCB-US | PCB Transformers | Federal ASTM Other | Click Here | None Found |
| PCS-US | Historical Permit Compliance System for Clean Water Act | ERS Supplemental Govt Sources | Click Here | None Found |
| Perch1-CA | Perchlorate Confirmed Contaminant Sites | ERS Supplemental Govt Sources | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|-------------------|--|-------------------------------|----------------------------|----------------|
| Perch2-CA | Perchlorate Confirmed Contaminant Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| PR-MOA-CA | Polanco Redevelopment MOA Sites | State/Tribal ASTM Other Med | Click Here | None Found |
| Project-CA | Project - Multipurpose Site Type | ERS Supplemental Govt Sources | Click Here | None Found |
| Proposed-NPL-US | Proposed NPL Sites | Federal NPL | Click Here | None Found |
| RADINFO-US | Radiation Information Database | ERS Supplemental Govt Sources | Click Here | None Found |
| RCRA-CESQG-US | Resource Conservation and Recovery Act, Conditionally Exempt Small Quantity Generators (aka RCRA CESQG) | Federal RCRA Generators | Click Here | None Found |
| RCRA-COR-US | Resource Conservation and Recovery Act, - Corrective Actions (aka RCRA CORRACTS) | Federal RCRA CORRACTS | Click Here | None Found |
| RCRA-LQG-US | Resource Conservation and Recovery Act, Large Quantity Generators (aka RCRA LQG) | Federal RCRA Generators | Click Here | None Found |
| RCRA-NON-US | Resource Conservation and Recovery Act, Non-Hazardous Generators (aka RCRA Non-Haz, RCRA NonGen, RCRA No longer Regulated) | Federal RCRA Generators | Click Here | 2 |
| RCRA-SQG-US | Resource Conservation and Recovery Act, Small Quantity Generators (aka RCRA SQG) | Federal RCRA Generators | Click Here | None Found |
| RCRA-TSDF-US | Resource Conservation and Recovery Act -, Treatment, Storage, and Disposal Facilities (aka RCRA TSD, RCRA TSDF) | Federal RCRA non-CORRACTS TSD | Click Here | None Found |
| Response-CA | State Response Sites and National Priorities List (NPL) | State/Tribal NPL | Click Here | None Found |
| RFG-Lab-US | Reformulated Gasoline (RFG) | ERS Supplemental Govt Sources | Click Here | None Found |
| RMP-US | Risk Management Plans | ERS Supplemental Govt Sources | Click Here | None Found |
| ROD-US | Records of Decision | ERS Supplemental Govt Sources | Click Here | None Found |
| SAA-Agreements-US | Sites with Superfund Alternative Approach Agreements | Federal ASTM Other | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|-------------------------------------|---|--------------------------------------|----------------------------|----------------|
| School-Active-CA | EnviroStor Database School Active Sites (aka School Property Evaluation Program, SCH) | State/Tribal Voluntary Cleanup Sites | Click Here | None Found |
| School-NFA-CA | EnviroStor Database School Active Sites (aka School Property Evaluation Program, SCH) | State/Tribal Voluntary Cleanup Sites | Click Here | None Found |
| School-Other-CA | EnviroStor Database School Active Sites (aka School Property Evaluation Program, SCH) | State/Tribal Voluntary Cleanup Sites | Click Here | None Found |
| SDWIS-US | Safe Drinking Water Information System | ERS Supplemental Govt Sources | Click Here | None Found |
| SGV-Deep-Plumes-CA | San Gabriel Valley Deep Plumes | State/Tribal Solid Waste | Click Here | None Found |
| SGV-Shallow-Plumes-CA | San Gabriel Valley Shallow Plumes | State/Tribal Solid Waste | Click Here | None Found |
| SGV-Shallow-Plumes-Puente-Valley-CA | Puente Valley Shallow Plumes | State/Tribal Solid Waste | Click Here | None Found |
| SLIC-Closed-CA | Geotracker - The Spills, Leaks, Investigation & Cleanup (SLIC), Closed Cases | Emergency Release Reports | Click Here | None Found |
| SLIC-Open-CA | Geotracker -Spills, Leaks, Investigation & Cleanup (SLIC), Open Cases | Emergency Release Reports | Click Here | None Found |
| SML-CA | Site Mitigation List | State/Tribal ASTM Other Med | Click Here | None Found |
| SP-CA | Sampling Points | ERS Supplemental Govt Sources | Click Here | None Found |
| Spills-SSO-CA | Sanitary Sewer System | ERS Supplemental Govt Sources | Click Here | 1 |
| SSTS-US | Section 7 Tracking System | ERS Supplemental Govt Sources | Click Here | None Found |
| State-Response-Active-CA | EnviroStor State Response Active Sites | State/Tribal NPL | Click Here | None Found |
| State-Response-NFA-CA | EnviroStor State Response NFA Sites | State/Tribal NPL | Click Here | None Found |
| State-Response-Other-CA | EnviroStor State Response Other Sites | State/Tribal NPL | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|-------------------------|---|-----------------------------------|----------------------------|----------------|
| Superfund-Active-CA | Envirostor Superfund Active Sites (aka BEAP, CalSites, Brownfields and Environmental Restoration Program) | State/Tribal CERCLIS Equivalent | Click Here | None Found |
| Superfund-NFA-CA | EnviroStor Superfund NFA Sites (aka BEAP, CalSites, Brownfields and Environmental Restoration Program) | State/Tribal CERCLIS Equivalent | Click Here | None Found |
| Superfund-Other-CA | EnviroStor Superfund Sites (aka BEAP, CalSites, Brownfields and Environmental Restoration Program) | State/Tribal CERCLIS Equivalent | Click Here | None Found |
| SWIS-CA | Solid Waste Information System | State/Tribal Landfill/Solid Waste | Click Here | None Found |
| SWLF-US | Solid Waste Facilities | Federal Solid Waste | Click Here | None Found |
| SWRCY-CA | Beverage Container Recycler Database | State/Tribal ASTM Other Med | Click Here | None Found |
| TierPer-CA | Tiered Permits | ERS Supplemental Govt Sources | Click Here | None Found |
| TOMS-CA | Topographically Occurring Mine Symbols | ERS Supplemental Govt Sources | Click Here | None Found |
| Tribal-Air-US | Tribal Air Permitted Facilities | ERS Supplemental Govt Sources | Click Here | None Found |
| Tribal-LUST-Closed-Reg9 | Tribal Leaking Underground Storage Tanks, Region 9 (aka Indian Lust) | Federal LUST | Click Here | None Found |
| Tribal-LUST-Open-Reg9 | Tribal Leaking Underground Storage Tanks , Region 9 (aka Indian Lust) | Federal LUST | Click Here | None Found |
| Tribal-ODI-US | Tribal Open Dump Sites | Federal Solid Waste | Click Here | None Found |
| Tribal-UST-Reg9 | Tribal Underground Storage Tanks (aka Tribal UST) | Federal UST | Click Here | None Found |
| Tribal-VCP-US | Tribal VCP | Federal Tribal VCP | Click Here | None Found |
| TRIS2000-US | Historical Toxics Release Inventory System | ERS Supplemental Govt Sources | Click Here | None Found |
| TRIS2010-US | Toxics Release Inventory System | ERS Supplemental Govt Sources | Click Here | None Found |
| TRIS80-US | Historical Toxics Release Inventory System | ERS Supplemental Govt Sources | Click Here | None Found |
| TRIS90-US | Historical Toxics Release Inventory System | ERS Supplemental Govt Sources | Click Here | None Found |
| TSCA-US | Toxics Substance Control Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| UIC2-CA | Injection Wells | ERS Supplemental Govt Sources | Click Here | None Found |
| UIC-CA | Underground Injection Control Wells | ERS Supplemental Govt Sources | Click Here | None Found |

| ABREVIATION | DATABASE FULLNAME | DATABASE CATEGORY | DATABASE DETAILS LINK | TOTAL LISTINGS |
|---------------------|---|--------------------------------------|----------------------------|----------------|
| UMTRA-US | Historical Uranium Mill Tailings Remedial Action Sites | ERS Supplemental Govt Sources | Click Here | None Found |
| USGS-Waterwells-US | Ground Water Site Inventory | ERS Supplemental Govt Sources | Click Here | None Found |
| UST-Abandoned-CA | Abandoned UST Initiative (aka Inventory of Abandoned Tank Sites) | State/Tribal UST | Click Here | None Found |
| UST-CA | Geotracker - Underground Storage Tanks | State/Tribal UST | Click Here | None Found |
| UST-Closed-CA | UST Case Closure Review Denials and Approved Orders (aka Closure of Underground Storage Tank (UST) Cases) | State/Tribal UST | Click Here | None Found |
| USTComp-CA | Previously Abandoned Tanks Now in Compliance (aka Compliance UST) | State/Tribal UST | Click Here | None Found |
| UST-CRSP-CA | Underground Storage Tanks | State/Tribal UST | Click Here | None Found |
| UST-Priority-CA | UST Cleanup Fund Priority List | State/Tribal UST | Click Here | None Found |
| UST-Proposed-CA | Proposed Closure of UST Cases (aka UST Proposed for Closure) | State/Tribal UST | Click Here | None Found |
| Vapor-Intrusions-US | Vapor Intrusion Database | ERS Supplemental Govt Sources | Click Here | None Found |
| VCP-Active-CA | EnviroStor VCP Active Sites | State/Tribal Voluntary Cleanup Sites | Click Here | None Found |
| VCP-NFA-CA | EnviroStor Database VCP NFA Listing | State/Tribal Voluntary Cleanup Sites | Click Here | None Found |
| VCP-Other-CA | EnviroStor VCP Other Sites | State/Tribal Voluntary Cleanup Sites | Click Here | None Found |
| WDR-CA | Waste Discharge Requirements | ERS Supplemental Govt Sources | Click Here | None Found |

UN-MAPPABLE OCCURRENCES

The following occurrences were not mapped primarily due to incomplete or inaccurate address information. All of the following occurrences were determined to share the same zip code as the area searched. General status information is given with each occurrence along with any address information entered by the agency responsible for the list.

| ID | Facility Name | Address | Database | Status |
|---------------------------------|---------------|---------|----------|--------|
| No "un-mapped" sites requested. | | | | |

DISCLAIMER, LIMITS AND LIABILITIES

All of the data presented in this report was garnered from public information maintained by governmental agencies. **Environmental Record Search (ERS)** cannot ensure that the data, which has been entered and maintained by others, is complete and/or accurate. Any, and all omissions, errors, negligence, accidentally or otherwise within the data received by **ERS** is assumed to be caused by others and **ERS** cannot and does not assume, take, or acknowledge any liability whatsoever for their respective data. The extrapolation of the mapped locations is based solely on the accuracy of the data provided by others. Prior to relying completely on any mapped location within this report, its accuracy should be verified using other means such as further documentation or a field visit. **ERS** makes no representation, warranty or guaranty, express or implied regarding the accuracy of the data entered and maintained by others or the suitability of the data received from others in this report for a certain task or interpretation.

The data presented in this report should only be interpreted by an experienced environmental professional, as per EPA definition, that completely understands the potential inaccuracy of the data derived from others, the possible existence of contaminated occurrences that have not been listed, and the possibility that the governmental database misrepresents the actual status of an occurrence or listing. Prior to relying completely on any of the data within this report, an environmental professional should verify the accuracy of the information presented unless one of ERS's Environmental Professionals has interpreted the data and/or report.

It is important that the reader and/or end user of this information realize that the data gathered has not been verified for its accuracy or completeness in any way by **ERS**. With billions of records, this is an impossible task for any Company. As much as possible, the data is presented unchanged and unaltered to represent the actual data produced by these agencies. This insures the integrity of the data for the end user.

ERS does however stand behind its representation of the data, any manually plotted occurrences, any risk determinations and all other items directly under its control. This report does comply (as far as the data is reasonably ascertainable as outlined in both the following standards) with section 8.2.1 of ASTM 1527-13 – Standard Environmental Record Sources and EPA's 40 CFR Part 312, All Appropriate Inquiries. **ERS** does ensure that the data is accurately reproduced from the original source. **ERS** backs the reporting of the data with \$3,000,000 of General and Environmental Professional Liability (errors and omissions) Insurance!

The **ERS** logo, name, report design, presentation, maps, tables, etc., are the exclusive property of **ERS** and its parent company and affiliates. Except as provided below, information or images contained in this report may not be reproduced or distributed in whole or in part by any means without the prior written permission from **ERS**. United States and international copyright laws protect any and all reports produced by **ERS**.

The person or entity that purchased this report may make up to five (5) copies of the entire report or any part of it for archival purposes or to include as part of another report. All copyright information must remain intact and not be modified in any way.

Environmental Record Search (ERS) and their respective products/reports (i.e. RecCheck, LenderCheck, Environmental Screen, etc.) as well as their respective business operations, are **NOT** associated in any way with nor related to, First American Commercial Real Estate, Inc. (FACRES) and/or the First American Family of Companies.

Maps throughout this report were created using ArcGIS® software by ESRI. ArcGIS® and ArcMap™ are the intellectual property of ESRI and are used herein under license. Copyright © ESRI. All rights reserved. For more information about ESRI® software, please visit www.esri.com. Topographic imagery used in maps throughout this report are Copyright © 2011 National Geographic Society. Street and aerial "hybrid" imagery used in maps throughout this report are Copyright © 2010 Microsoft Corporation and its data suppliers.

APPENDIX D

RESUMES



Environmental Consulting ~ Project Management ~ Technical Management ~ Contract & Project Work

JEN MOSER, P.G.

Phone: (510) 376-5771 ~ E-mail: jenmoser@mygemgroup.com

PROFILE

- Resourceful and solution-driven environmental consultant
- 25+ years' experience in site characterization and remediation projects of up to \$10+ million
- 8+ years' experience in exploration, development, open pit and underground mining
- History of implementing new technologies to solve problems before projects are impacted
- Skilled in managing field operations, including determination of approach and equipment
- Experienced in operations and maintenance of a landfill
- Co-authored report published in The Military Engineer (the Society of American Military Engineers), *Historical Range Assessment at Fort Ord*

PROFESSIONAL EXPERIENCE

GEM Group, Inc. dba Tom Edwards & Associates

2005-present

Environmental and Geological Consultant

- Prepare plans, investigation, remediation, and completion reports
- Conduct Phase 1 Environmental Site Assessments (ESAs)
- Determine the need for further site investigation and/or remedial action and direct implementation
- Prepare proposals and budgets
- Interface extensively with Federal, State, County, and Local government agencies on project permits, investigations, evaluations, and recommendations
- Managed the evaluation and remediation of contaminated soil and ground water, from planning to delivery and reporting in compliance with 100% of regulatory requirements (former Fort Ord)
- Coordinated DGM and MEC removal from ranges requiring soil remediation
- Supervised operations and maintenance of landfill, including LFG extraction, treatment, and monitoring

AARON ENVIRONMENTAL / HARZA / ONSITE ENVIRONMENTAL / ITSI

1994-2005

Geologist

- Supervised excavation of contaminated soil at Superfund site
- Conducted Phase 1 ESAs and Phase II investigations
- Prepare plans, investigation, remediation, and completion reports
- Prepared proposals and budgets
- Presented plans and project status to clients and regulatory agencies
- Managed the evaluation and remediation of contaminated soil, from planning to delivery and reporting in compliance with 100% of regulatory requirements (former Fort Ord)
- Supervised operations and maintenance of landfill, including LFG extraction, treatment, and monitoring

TETRA TECH INC.

1993-1994

Project Geologist

- Remedial Investigation and Feasibility Studies at Superfund sites
- Supervised drilling of soil borings, installation of ground water monitoring wells, trenching on landfill areas, soil, sediment, ground water, and surface water sampling

ARMENONIC DEL ECUADOR

1989-1991

Consultant Resident Geologist

- Responsible for startup and takeover of geology department of Armenonic del Ecuador's' underground complex silver mines
- Mapped, evaluated, and proposed tunnels to intercept high-grade complex silver veins
- Hired and trained personnel and developed SOPs for geology department
- Assessed effects of tunneling, milling and tailings dam on drinking water supply of nearby towns

BENGUET CORPORATION

1983-1989

- Mapped, evaluated, delineated, and supervised underground and open pit mining
- Evaluated effects of drilling and underground mining on water supplies
- Supervised tunneling and diamond core drilling during exploration and development of underground and open pit mines
- Planned and supervised access road and site preparation
- Performed resource evaluation of project sites – field geology technique reviews
- Recommended improved mapping and sampling techniques

CERTIFICATIONS

- Professional Geologist, 2001
- OSHA (Occupational Safety & Health Administration)
 - 8-Hour OSHA Refresher Course (Annual)
 - 8-Hour OSHA Supervisory Training
 - 40-Hour OSHA Training



Environmental Consulting ~ Project Management ~ Technical Management ~ Contract & Project Work

MIKE ERVING, JUNIOR GEOLOGIST

Phone: (626) 513-5095 ~ **E-mail:** mikeerving@mygemgroup.com

PROFILE

- Eager to learn and excel in the environmental field
- Self-driven, results-oriented, and diligent professional

PROFESSIONAL EXPERIENCE

GEM Group, Inc.

2018-Present

Junior Geologist

- Prepare Transaction Screen and Phase I Environmental Site Assessment reports, including:
 - Interpret information gathered from third-party computer-generated reports.
 - Request and review public agency records from various cities and counties.
 - Site reconnaissance and visual site inspections throughout Southern California.
 - Review of historical information including topographic maps, fire insurance maps, city directories, and aerial photographs.
- Assist Project Geologist in conducting soil, soil gas, groundwater, and indoor air investigations.
- Assist Project Geologist in completion of other reports including desktop reviews.

Geoscience Support Services Inc.

2015-2016

Intern

- Participated in site investigations including sample collection, well transducer monitoring, and well drilling.
- Assisted in the physical completion of reports.
- Prepared clerical work for the overall efficiency of the office.
- Assisted in the design and completion of website.

EDUCATION

Gustavus Adolphus College, Saint Peter, MN

2017

- Geology; Bachelor of Arts

CERTIFICATIONS

- HAZWOPER, 40 Hour General Site Worker, Occupational Safety & Health Administration (OSHA) (April 2018)
- HAZWOPER, 8 Hour Refresher Course, OSHA (April 2019)